AMERICAN MACHINIST INDEX

McGRAW-HILL PUBLISHING COMPANY, INC., 330 WEST 43ND STREET, NEW YORK 36, N. Y.

CONTENTS OF VOLUME 98 JANUARY TO DECEMBER, 1954

A

Abrasives:

Chemical reaction—the grinder's friend or foe? ..... Sept. 13—197
Contact wheels influence abrasive-belt performance. Direk Olton ..June 21—121
Cradle grinding makes abrasive belts more automatic ..... Feb. 15—153
Grinding wheels have three components: abrasive grit, bonding agents, and pores. N. P. Robie (tables) ..Aug. 2—114
How abrasive-belt grinding improves taper sheet production. J. R. Burns Nov 22—126

Acrylics—How to machine acrylic plastics. Dr. O. L. Pierson (report) (tables) Feb. 1—113-120

Adaptors—Release tubing die. William Hartmann. (P.I.) ..... Dec. 20—116
Turret misalignment corrected with adapter. N. Feinberg. (P.I.) . July 19—148

Administration—No raids on machine tool reserves (ed) ..... Aug. 30— 83

Airborne Instruments Laboratory—Plan and program to make your own engineers. H. J. Gresens ..... Feb. 15—127

Air Compressors:

Aeration by air injection used in new foam-cooling method. Mason & Weber (chart) ..... Apr. 12—174
Air power used for machines at Kwikset Locks, Inc. ..... Apr. 26—106
Eight ways to make pneumatics practical. L. H. Kirk ..... June 21—130

Aircraft Construction:

Britain's long-range turboprops now in production ..... Oct. 25—179
Chemical milling of aluminum sections to cut down airframe weight .... Sept. 13—200
Convair—methods of tooling with plastics. H. H. Rosenbaum ..... Mar. 15—121
Conventional tools machine titanium for aircraft-gun parts. Roland Satterlee Aug. 30— 94
Dodge sets up West Coast's first major aircraft propeller plant ..... Mar. 15—180
Flow coating lines apply zinc chromate primer to aircraft parts .... Sept. 27—154
Hand forming—machine style. N. L. Whipple ..... Nov. 22—141
High-pressure forming press for jet planemaking operations .... Sept. 27—158
How Ryan forms and welds titanium Dec. 6—138
How to coordinate subcontracting to meet production schedules. G. E. Fouch (report) (charts) . Feb. 15—137-144
How to form integrally stiffened skins. W. T. Kluge (report) ...Nov. 22—129-140
Longest continuous flow coating paint line at Douglas. ..... Oct. 11—190
Modern planes from hand forging. Sept. 27—157
National Aeronautic Production Forum Apr. 26—152
New British design in rocket-propelled model planes ..... Sept. 27—161
Pinball machines are salvaged to go into laboratory test equipment at Boeing Sept. 13—169
Process evaluation pays long-term dividends at Fairchild. W. M. Stocker, Jr. (report) ..... June 21—133-140
Production problems on supersonic planes. A. Ashburn (report) ..... July 5—129-144
Royal Gull, twin-engine amphibian manufactured by Royal Aircraft Corp. Sept. 13—202
Ryan Aeronautical saves $20,000 a month with air-tools ..... Mar. 15—153
Spar-skin mill machines entire plane sections in a single operation at Douglas Aircraft's Plant ..... June 7—170
TASA goes to Washington to get government recognition of aircraft in national defense ..... July 5—163
Titanium fasteners: planemakers pool technology to improve them . Aug. 30—128

Aligning workpiece speeded with disconnected table worm. Gustav Weinberg (P.I.) ..... Feb. 1—126

Allis Chalmers Mfg. Co.—Mist cooling systems improve machining operations. Thuma & Sdano (report) ..... Aug. 2—117
Study of heat vs. cold showed no relationship between temperature and accidents. Ann Stresau (charts & tables) ..... Dec. 20—114

Alloys:

Hard bronze inserts for drawing and forming stainless dies without scratches. Arnold Walz ..... Aug. 2—106
How to understand heat-treatment processes. Samuel Storchheim (charts) Apr. 26—130
New alloy designations for wrought-aluminum and aluminum alloys (tables) (Ref. Bk. Sheet) Pts 1 & 2 ..... Sept. 13—187
Now titanium can be furnace-brazed (charts) ..... Aug. 16—117
Titanium alloy fasteners to replace heavy metal fittings and fasteners in airplanes ..... Aug. 30—128

Aluminum:

Chemical milling of aluminum sections for aircraft ..... Sept. 13—200
Hot-extruded aluminum pistons ... May 10—172
Hot extruding aluminum fan blades to 0.001-in. tolerance in 100-ton press .. Feb. 15—184
How to stretch-form aluminum. J. M. Adle (report) ..... July 19—133-140
How to bend aluminum tube and bar. J. M. Adle (report) ..... May 24—137-144
How to nickel-plate aluminum for solder joining. Wm. M. Stocker, Jr.. June 7—154
New wrought-aluminum designations (tables) (Ref. Bk. Sheets) Pts. 1 & 2 Sept. 13—187
Spot welding aluminum (Ref. Bk. Sheets) (chart and tables) Pts. 1, 2 & 3 ..... Jan. 4—123
Stretch aluminum plate to reduce machining distortion. Lawler & Binkley (tables) ..... Mar. 15—128

American Gear Manufacturers Assn.—meeting ..... June 21—170
Semi-annual Chicago meeting announces new gear standards ..... Nov. 8—182

American Institute of Electrical Engineers—7th annual conference..... Nov. 8—175

American Machine Tool Distributors' Assn.—Annual meeting sees replacement as machine tool market's biggest potential. Nov. 8—176
To expand services to machine tool industry ..... Mar. 15—180

American Machinist:

Index of metalworking production (charts & tables) ..... Mar. 29— 97
1955 Production Planbook for Metalworking (charts & tables) ..Mid-Nov.
1954 prize-winning Practical Ideas ... Mid-Nov.—J1-7
1954 production preview of new metalworking equipment, parts, and materials ..... Jan. 18—121-264

American Machinist Reports:

Artists sculpture mica dies. J. P. Wright (charts & tables) ..... Sept. 13—145-160
Canada—Metalworking's land of promise ..... May 24—129-136
Chip breaker balanced design. E. K. Henriksen (charts & tables) Apr. 26—117-124
Electrical-discharge machining. Harding, Matulaitis & Stoke. Mar. 15—137-148
Handbook of workholding devices. H. E. Linsley. Pt. 2 Stationary devices. Oct. 11—145-160
High-speed trepanning. W. M. Stocker Jr. ..... Jan. 4—105-114
How to bend aluminum tube and bar. J. M. Adle ..... May 24—137-144
How to choose hydraulic presses for metal forming operations. H. D. Thweatt ..... Mar. 29—115-126
How to control corrosion. C. D. Emerson ..... Dec. 6—145-160
How to coordinate subcontracting to meet production schedules. G. E. Fouch (charts) ..... Feb. 15—137-144
How to form integrally stiffened skins. W. T. Kluge ..... Nov. 22—129-140
How to machine acrylic plastics. Dr. O. L. Pierson ..... Feb. 1—113-120
How to stretch-form aluminum. J. M. Adle ..... July 19—133-140
How to understand annealing and hot working of metals. Samuel Storchheim (charts & tables) . Sept. 13—161-168
How to understand cold working of metals. Samuel Storchheim (charts & tables) ..... Aug. 30—101-108
How to understand heat-treatment processes. Samuel Storchheim (charts) Apr. 26—125-134
How to work stainless steel. R. E. Paret (tables) ..... Sept. 27—129-140
How to work steel. Ashburn & Le Grand (charts & tables) (report) Mid-Nov.—33-160
How to work tomorrow's metals—tantalum, columbium, zirconium, beryllium. ..... Apr. 12—188-208
How tools made the world in which we live. E. J. Tangerman (flowsheet) Dec. 20—101-108
Mist cooling goes to work. Pt. 1 Mist cooling systems improve machining operations. Thuma & Sdano. Pt. 2 Mist cooling helps some planer jobs. Feuerpfeil, Titus & Thuerwach. Aug. 2—117-132
New look at wormgear hobbing. Ernest Wildhaber ..... June 21—149-152
New tools . . . automated make '55 cars. ..... Nov. 8—117-164
Non-cylindrical contours . . . how you can grind them. J. P. Wright May 10—137-156
Numerical control, what it means to metalworking. Stocker Jr. & Emerson (table) ..... Oct. 25—133-156
Process evaluation pays long-term dividends. W. M. Stocker, Jr. ..... June 21—133-140
Production problems on supersonic planes. A. Ashburn ..... July 5—129-144
Realistic depreciation rates. Burnham Finney (chart) ..... Mar. 1—113-120
Small shops can use automation too. J. B. Cunningham (charts) ..... Apr. 12—177-184
Supervisors for tomorrow. Wm. M. Stocker, Jr. ..... Aug. 16—133-140
Thermal number measures efficiency of metal cutting. K. J. Trigger (charts) June 7—145-152

American Management Assn.—Special Conference on Capital Equipment Replacement ..... May 24—169

American Society of Mechanical Engineers—Milwaukee meeting—automation discussion ..... Sept. 27—156
Milwaukee meeting—chemical reaction discussion ..... Sept. 13—197
N.Y. meeting discusses automation.... Dec. 20—132

American Society of Tool Engineers—Industrial Exposition and Conferences... Apr. 12—250
Tool Show highlights ..... May 10—186
Industrial exposition, Philadelphia. New equipment and tools....Apr. 12—217

Angles:

Center positioning gage for angular wheel-truing. H. J. Gerber (P.I.).. Mar. 1—127
Clamped carbide tips hollow-ground at Caterpillar Tractor to make rake angles positive. Matt Aljanich. Jan. 4— 89
Compensated angles add life to complicated form tools. R. G. Vare (P.I.) Apr. 12—215
Formulas for adjacent triangles. J. R. Paquin (Ref. Bk. Sheet)....Jan. 18—267
New drill angles for titanium from Republic Aviation ..... June 21—142
Normal thread angles and bottom flats (Acme). Donald Sweet (tables) (Ref. Bk. Sheets) Pts. 1 & 2 Sept. 27—147

Anti-trust law—Clayton Act has teeth, steel firms find ..... Oct. 25—174

Apprentices—Tool and diemakers trained at John Volkert Metal Stampings. Apr. 26—156
Training of apprentices for diemakers at Schneider & Marquard. J. P. Wright (charts & tables) (report).. Sept. 13—145-160

Arbors:

Jack removes arbors from drill chucks. Henry George (P.I.) ..... Mar. 1—128
Soft die and hard arbor taper tubes. F. E. Chase (P. I.) ..... Sept. 27—141
Threaded arbor saves straddle-mill setup time. Henry George (P.I.) Apr. 26—138

(ed) Editorial (P.I.) Practical Ideas

Threaded arbor unsticks work. Carl Hoff (P.I.) ..... Oct. 25—160
Arc machining — Electrical-discharge machining report. Harding, Matulaitis & Stoke ..... Mar. 15—137-148
Watertown Arsenal applies electrical discharge machining. Anderson Ashburn (charts) ..... Apr. 12—185

Atomic Energy Commission:

Atomic electric power: a tough, tricky equipment market opens ..... June 7—170
McGraw, F. H., & Co. uses new techniques to build Paducah, Ky., plant Jan. 4— 92
Robot-run tools machine "hot" materials at Oak Ridge. Stewart E. Dismuke (charts) ..... Apr. 12—161
Summary of reports on zirconium shop practice ..... Apr. 12—199
Atomic-submarine power plant—To machine radioactive materials. S. L. Lindbeck Apr. 12—166

Automation:

AIEE Conference on machine tools deals with automation ..... Nov. 8—175
ASME's Milwaukee meeting discusses automation ..... Sept. 27—156
ASME's New York meeting discusses automation ..... Dec. 20—132
Automatic assembly of complex electronic assemblies ..... Mar. 15—186
Automatic polishing machine. F. E. Riley (P.I.) ..... June 21—145
Automatic welding fixture eliminates need for costly positioning. Troyer & Lorain, Jr. (chart) ..... Apr. 26—108
Automation combines standard lathes. E. J. Tangerman ..... Mar. 29—110
Automation is only the first step (ed) Sept. 13—127
Better think it over, Mr. Reuther! (ed) Dec. 6—127
Co-determination (ed) ..... Dec. 20— 87
Cold-forming gears and splines June 21—169
Continuous-cast bar machined on automatic bar machine ..... Oct. 25—121
Contour welding performed automatically ..... Feb. 1—107
Drum-lifting tongs handle pots of radioactive parts automatically. A. A. Denst (P.I.) ..... Oct. 25—163
Eberhard MFG's automatic foundry ... Oct. 25—177
Engineers talk new tooling at Purdue .. June 7—172
Film-index system controls riveting machine at Convair ..... July 19—160
GE electronic system adds automatic machine control for job-lot production ..... Feb. 15—182
Is automation your dish? (ed) .. Feb. 15—119
New tools . . . automated make '55 cars (report) ..... Nov. 8—117-164
Note from Moscow (ed) ..... May 10—119
Numerical control, what it means to metalworking. Stocker Jr. & Emerson (table) (report) .... Oct. 25—133-156
One machine automated . . . or a whole line (cover) ..... Nov. 8— 2
Pushbutton plating at Pontiac saves nickel ..... Dec. 20—136
Railroad axles roller-bearinged at freight-car production speeds at American Car & Foundry. E. J. Tangerman Jan. 4—130
Reuther's report on automation. Dec. 6—190
Robot-run tools machine "hot" materials at Oak Ridge. Stewart E. Dismuke (charts) ..... Apr. 12—161
Russians apply automation to 20-yr-old machines. David Scott ..... Oct. 11—164
SAE discusses automation ... Apr. 12—258
Second industrial revolution?—automation of electronics ..... May 10—190
Silver brazing goes semi-automatic. Spiesz & Leuthner ..... May 10—121
Small shops can use automation too—report. J. B. Cunningham (charts) Apr. 12—177
Synchromation speeds output of standard machines. B. C. Brosheer. Dec. 20—110
Tubular parts are welded automatically. Roy Martin ..... Sept. 27—119
What are you doing about automation? (ed) ..... July 5—111

Automobile Construction:

Canadian transfer unit ups Ford output ..... June 21—166
Chrysler's new proving ground. July 5—163
Continental: Ford aims to recapture the carriage trade ..... May 24—168
Ford meets plastic sports car challenge with all-steel Thunderbird Mar. 1—141
Ford to build third proving ground ... Aug. 2—131
GM's $6-million Antwerp expansion to double its European output ... Oct. 11—195
Germany's rear-engined Porsche—small output, high craftsmanship .... Aug. 2—156
Kaiser to build 44,000 cars a year in Argentina ..... Oct. 25—179
New British design in sport cars .... Sept. 27—161
New tools . . . automated make '55 cars (report) ..... Nov. 8—117-164
Packard slates $50 million tooling for initial modernization move ... Mar. 15—183
Production tools for precision from Ford Instrument. W. M. Stocker, Jr. ..... June 21—117
Regenerative gas turbine developed by Chrysler Corp. ..... Apr. 12—259
Ten steps make sports-car tailpipes. Carl Koonter ..... Oct. 25—158
Volkswagen turns out 900 cars a day Aug. 2—157
West Coast auto output: a challenge to Detroit? ..... July 19—162
Awards—Ford Industrial Arts Awards Competition encourages kids with a mechanical bent ..... Aug. 16—159
NMBTA award presented at ASME meeting ..... Dec. 20—133
Axles—Railroad axles roller-bearinged at freight-car production speeds at American Car & Foundry. E. J. Tangerman Jan. 4—130
Rebuilt 50-ton press burnishes axle housings. E. D. White (P.I.) ..... Mar. 1—125

B

Babbitt—How to babbitt a large bearing. H. E. Linsley ..... Aug. 30— 98
Balancing—Simplified static balancing. J. W. Reid (Ref. Bk. Sheets) Pts. 1 & 2 .. Oct. 11—179
Batteries for flashlights — 3 colors from 1 inventory with pre-coated metal coil Jan. 4—104
Beams—H-beam supports yokes for easy drilling. A. V. Hogg (P.I.) ... Mar. 1—127

Bearings:

Ball-bearing fixture rolls out copper wire. M. Barash (P.I.) ..... Apr. 26—139
Ball-bearing telescoping drive. M. L. Parsons (P.I.) ..... Aug. 30—114
How to babbitt a large bearing. H. E. Linsley ..... Aug. 30— 98
Oil groove cut in cast iron sleeve bearing. Clifford Molloy (P.I.) .... Apr. 12—216
Railroad axles roller-bearinged at freight-car production speeds at American Car & Foundry. E. J. Tangerman Jan. 4—130
"Wicking gun" helps invert wicks into bearings. Jack Schofield (P.I.) Sept. 13—181

Belting:

Belt finishing of carbide tools proves effective. F. J. Lennon, Jr. .... Feb. 1—104
Belt grinding of titanium (Ref. Bk. Sheets) (charts) Pts. 1, 2 & 3 ... June 7—163
Contact wheels influence abrasive-belt performance. Dirck Olton .... June 21—121
Cradle grinding makes abrasive belts more automatic ..... Feb. 15—153
How abrasive-belt grinding improves taper sheet production. J. R. Burns .. Nov. 22—126
Washer cutter forms emergency belts. William Adams (P.I.) ..... Jan. 4—119

Bending:

How to bend aluminum tube and bar. J. M. Adle (report) ... May 24—137-144
Redesigned bending die cuts one operation. H. Dahl (P.I.) ..... Jan. 4—119
Simple wire-bending die. Federico Strasser (P.I.) ..... June 21—147
Versatile producer . . . the press brake. J. W. Matthewman (tables) Pt 4. For safety, bend according to the rules Nov. 22—116

Beryllium—techniques for development. Lowenstein, Kaufman, Arnold & Bishop (report) (charts) ..... Apr. 12—203

Blocks:

Hold-down screw blocks effective on planers. A. G. Liska (P.I.) .. Nov. 22—152
Measuring the first "jo" block .. Apr. 12—255
Right-angle V-block for circular layout. Walter Trimailo (P.I.) ..... Feb. 15—167
Rotating guide block aids taper cut. S. Hahne (P.I.) ..... Aug. 2—138

Bolts:

Cotton in lockscrew hole to avoid damage to threads of bolt. G. R. Milner (P.I.) ..... Dec. 20—117
Production methods are key to improved bolt design. M. Brenner ..... July 5—146
Slot in thread cleans bolts. C. L. Martin (P.I.) ..... Mar. 1—128

Bores and Boring:

American Machinist production nuggets of machining (charts & tables) ..... Mid-Nov.—B1-37
Boring three parts at once (cover) .... June 7— 2
Dodge gages V-8 bores in the machine shop. B. S. MacPhail ..... Oct. 11—134
Flexible tool support aids cutting tapered hole. J. W. Wallace (P.I.) July 5—150
Ford precision bores valve-stem holes (cover) ..... Mar. 1— 2
High-speed trepanning at Bethlehem Steel. W. M. Stocker, Jr. (report) .. Jan. 4—105-114
How U.S. Navy probes bores. J. A. Penn ..... Mar. 15—160
Inexpensive boring bar holder. H. N. McAllister (P.I.) ..... July 19—147
Inexpensive boring head. H. Koslow (P.I.) ..... July 5—151
Internal "steadyrest" cuts boring bar chatter. H. J. Gerber (P.I.) .. June 21—147
"Jet Bore" probably most powerful machine tool (cover) ..... Apr. 26— 2
Jig borers for juke boxes (cover) .. Feb. 1— 2
Jig borers in profusion (cover) .. Aug. 2— 2
Plunge cut and helix produce boring tool. Allan Clarke (P.I.) .... Mar. 29—130
Re-boring cylinder heads with nearly automatic machine ..... Apr. 12—250
Setup bores large work on lathe with short bed. M. L. Gupta (P.I.) Dec. 6—176
Special cutting heads finish 1066 holes. Carl Jensen (P.I.) ..... May 10—173
Spherical bore milled with single-point tool. J. E. Harwood (P.I.) . Mar. 29—129
Three-position boring bar speeds setups. Larry Harrington (P.I.) .... Aug. 30—115
World's largest boring mill? Germany's Schiess AG built, but Russia has it Mar. 1—138

Brazing:

Gas burners braze turbine blades. E. M. Mickley ..... Dec. 6—170
How to braze carbide-tipped tools (Ref. Bk. Sheet) ..... Dec. 20—123
Silver brazing goes semi-automatic. Spiesz & Leuthner ..... May 10—121
Titanium can be furnace-brazed (charts) Aug. 16—117

Broaching and Broaching Machines—American Machinist production nuggets of machining (charts & tables) . Mid-Nov.—B1-37
Browne & Sharpe Mfg. Co.—New wrinkles for an old plant. R. Sheets ..... June 7—129
Burnishing—Rebuilt 50-ton press burnishes axle housings. E. D. White (P.I.) Mar. 1—125
Burring—Carbide bur "grinds" radius slot on hardened 8713 steel. E. J. Tangerman (charts) ..... Apr. 12—172
Cope talks on draw dies. S. R. Cope Pt. 19 Stampings often require burred or franged holes Sept 13—140; Pt. 20 Choice of die type depends on the burr Sept. 27—120; Pt. 21 Three kinds of burrs require different dies Dec. 6—166
Bushings—Second operation sped by drill-press fixture. Edward Schmidt (P.I.) .. Apr. 12—214
Split-bushing fixture simplifies staking. E. G. Filipowicz (P.I.) ..... Feb. 15—165

C

Calculations:

Circular form-tools corrections. I. Zorich (Ref. Bk. Sheets) ..... Mar. 29—135
Corrections for flat form tools. I. Zorich (Ref. Bk. Sheets) (charts) .. Mar. 29—133
Formula for multiple-lead threads speeds shop calculating. H. W. Holmdahl (P.I.) ..... Oct. 25—164
Formulas for adjacent triangles. J. R. Paquin (Ref. Bk. Sheets) .... Jan. 18—267
How to calculate exact wheel profiles for form grinding helical-gear teeth. Oliver Saari (table) ..... Sept. 13—172
"Metal-to-metal" involute gears. Oliver Saari ..... Dec. 20— 89

Cams—Cam feed speeds undercutting on 75-mm shell. S. F. Pasternak .. Apr. 26—110
Side cams on assembly die speed switch assembly. Federico Strasser (P.I.) Aug. 16—145

Canada—Canadian Trade Fair: eight nations compete for machine-tool business. June 21—166
Metalworking's land of promise (report) May 24—129-136

Capital—Metalworking 1954 outlook (charts) Apr. 26—150

Capital Goods:

Tool lease pros and cons ..... Apr. 12—252
US must look to less-developed countries for market ..... Oct. 11—189
US 1953 capital goods output tops 1952's $54 billion (charts & tables) .. Jan. 18—274

Carbides:

Belt finishing of carbide tools proves effective. F. J. Lennon, Jr. .... Feb. 1—104

(ed) Editorial (P.I.) Practical Ideas

Carbide bur "grinds" radius slot on hardened 8713 steel. E. J. Tangerman (charts) ..... Apr. 12—172
Carbide cuts carbide chipbreakers when Watertown Arsenal applies electrical-discharge machining. Anderson Ashburn (charts) ..... Apr. 12—185
Carbide tooling succeeds on automatics ..... July 19—158
Clamped carbide tips hollow-ground at Caterpillar Tractor. Matt Aljanich ..... Jan. 4— 89
Eaton is producing all but 2% of its carbide tool requirements ... Sept. 27—160
Electrical-discharge machining report. Harding, Matulaitis & Stoke ..... Mar. 15—137-148
Electrolytically-assisted carbide grinding cuts diamond consumption. Thibault & Anderson (tables) ..... Feb. 15—154
Russian design for cutting edge of single-point tools. Frank Sachs (charts) ..... Apr. 12—170
Tool cost cut is 59% with Kendex tooling ..... Nov. 22—146
220-ton press makes 2-ton carbide pieces ..... Mar. 15—185
Carbon dioxide—English technique cools tip . . . not chip, with CO_2 ..... Feb. 15—130
New concept machines titanium alloys and heat-resistant materials. G. H. DeGroat ..... Aug. 2—152

Castings:

Continuous-cast bar replaces sandcastings ..... Oct. 25—121
Fixture for castings with wrong draft angle. Fred Dewick (P.I.) .... Feb. 1—126
In-place babbitting aids spotfacing large casting. J. H. Rollin (P.I.) .. Mar. 15—164
Intricate investment castings require shop "savvy." J. P. Wright Nov. 22—120
Process evaluation pays long-term dividends. W. M. Stocker, Jr. (report) ..... June 21—133-140

Centering:

Center positioning gage for angular wheeltruing. H. J. Gerber (P.I.) ..... Mar. 1—127
Centering a keyseat cutter. F. Moser (P.I.) ..... Apr. 26—138
Indicator center-finder. John McCafferty (P.I.) ..... Sept. 13—183
Chains—Roller-chain links for odd jobs. Haim Murro (P.I.) ..... Mar. 29—127
Chemical milling—Is fast and cheap. Sept. 13—200

Chips:

Canny bulk handling saves chip and oil wastes. Lindsay & Graves .. Mar. 15—130
Carbide cuts carbide chipbreakers when Watertown Arsenal applies electrical-discharge machining. Anderson Ashburn (charts) ..... Apr. 12—185
Chip breaker balanced design. E. K. Henriksen (report) (charts & tables) ..... Apr. 26—117-124
Chipless manufacturing methods discussed by SAE ..... Apr. 12—258
High-speed trepanning at Bethlehem Steel gives attention to chip control. W. M. Stocker, Jr. (report) ..... Jan. 4—105-114
How to select chip breakers. E. K. Henriksen (Ref. Bk. Sheets) Pts. 1, 2 & 3 ..... May 10—179
Radial drills make chips by the ton. Leo Braun ..... May 24—148
Shorter chipbreakers save diamonds. W. A. Fanger ..... May 24—113
Westinghouse produces two refrigerators a minute with integrated production, continuous chip disposal. G. H. De Groat ..... May 10—157

Chucks and Chucking:

Drill chuck adapter for tailstock. P. L. Budwitz (P.I.) ..... June 21—148
Jack removes arbors from drill chucks. Henry George (P.I.) ..... Mar. 1—128
Know your magnetic chucks. H. Gifford ..... July 5—122
Lathe-chuck crane aids handling, storage. Terry & Stuart (P.I.) Nov. 22—148
Slotted aluminum step-chuck holds small rings. H. H. Ramm (P.I.) .. Aug. 30—115
Spanner wrench avoids chuck damage. Richard Cataldo (P.I.) ... Apr. 26—136
Spin re-entrant shapes when chuck cost is limited. Sams & Borodavchuk ..... Feb. 15—145
Vacuum chuck and special table increase milling range. R. W. Holmes (charts) ..... Apr. 12—210
Vacuum chuck holds thin strip for grinding. Robert Weidenhoft (P.I.) ..... Sept. 27—142
Workholding devices handbook. H. E. Linsley (report) Pt. 2 Stationary devices ..... Oct. 11—145-160

Clamps:

Erasers support thin parallels. Federico Strasser (P.I.) ..... June 21—145
Equalizing clamp for light work. Cliff Bossmann (P.I.) ..... June 21—148
Russians harness plastic mass for actuating medium ..... June 21—126
Sawtooth steps make versatile clamp. A. E. Fristedt (P.I.) ..... Oct. 11—172
Self-centralizing clamp aids milling flats. W. M. Halliday (P.I.) ..... Dec. 20—117
Simple clamping device holds channels for welding. Franz Eheim (P.I.) ..... Feb. 1—126
Simple device gages vise-held work. Jaan Wain (P.I.) ..... Oct. 25—164
Workholding devices handbook. H. E. Linsley (report) Pt. 2 Stationary devices ..... Oct. 11—145-160
Clayton Act—Anti-merger law has teeth, steel firms find ..... Oct. 25—174

Cleaning:

American Machinist production nuggets of heat treating, cleaning, finishing .. Mid-Nov.—G1-7
Scale—laundry soap cuts heat scale. W. Adams (P.I.) ..... Mar. 29—130
Slot in thread cleans bolts. C. L. Martin (P.I.) ..... Mar. 1—128
Tantalum and columbium properties and methods of working. J. W. Rose (report) (charts & tables) ... Apr. 12—189
Clutches—Starter-motor parts aid experimental work. H. Koslow (P.I.) .. Mar. 29—128
Coatings—Flow coating plane parts increases paint shop output 116% at Northrop ..... Sept. 27—154
Coils—Endless coil spring activates stripper fingers. Burnett Menkin (P.I.) .. Apr. 12—213

Comparators:

"Dieset comparator" easily made from stock parts. Jerry Coates (P.I.) ..... Oct. 11—175
Inexpensive shop comparator measures to 0.0001 in. G. Lee (P.I.) .. Dec. 20—118
Plate-glass extension adds capacity to comparator. Ottavio Cerullo (P.I.) ..... May 10—174
Contacts—UHF contacts formed four times faster. C. S. Selby ..... Feb. 1— 97
Containers—Marking of compressed-gas containers. F. R. Fetherstone (Ref. Bk. Sheet) ..... Sept. 13—191

Contour Machining:

Air-cylinder attachment aids VTL contouring. Alfred De Angelis (P.I.) ..... Dec. 20—116
Contour welding performed automatically ..... Feb. 1—107
Densified wood contouring (cover) ..... Nov. 22— 2
Densified wood cut by jigs and rigs ..... Nov. 22—147
Hard bronze inserts for drawing and forming stainless dies without scratches. Arnold Walz ..... Aug. 2—106
Non-cylindrical contours how you can grind them. J. P. Wright (report) ..... May 10—137-156
Perpetual motion saves money in contouring generator shaft ..... Oct. 25—122
Production problems on supersonic planes. A. Ashburn (report) ..... July 5—129-144
Simple contour-milling attachment. C. B. Weidner (P.I.) ..... July 5—149
Wound-up form tool unwinds to cut contours. C. Molloy (P.I.) ... Feb. 15—164
Consolidated Engrg. Corp.—Shop canteen (cover) ..... Feb. 15— 2
Construction—McGraw, F. H. & Co. uses new techniques to build new atom plant, Paducah, Ky. ..... Jan. 4— 92
Contractors—Progress payments ease off ..... May 10—193

Contracts:

Defense contracting: is small business getting the short end? ..... Mar. 29—144
Government contracts—MAPI recommendations ..... Dec. 20—136
New renegotiation regulations exempt small contractors ..... Sept. 27—158
Offshore procurement: US purse strings are tightening ..... June 21—174

Controllers:

Air speeds control-device assembly. D. S. Lisberger ..... Aug. 16—126
Numerical control, what it means to metalworking. Stocker Jr. & Emerson (table) (report) ..... Oct. 25—133-156
Robot-run tools machine "hot" materials at Oak Ridge. S. E. Dismuke (charts) ..... Apr. 12—161
Transistor and machine tool controls ..... Sept. 13—133

Conveyors:

Big plant tooling in a small shop. G. H. DeGroat ..... June 7—138
Fixture loads itself from conveyor (cover) ..... Oct. 11— 2
Flow coating conveyor lines apply zinc chromate primer to aircraft parts ..... Sept. 27—154
Longest continuous flow coating paint line at Douglas ..... Oct. 11—190
"New look" hits caterpillar plant ..... June 7—178
Telephones and conveyors speed schedules. W. A. Ring ..... Sept. 13—134
Westinghouse conveyor systems for fast production of refrigerators. G. H. DeGroat ..... May 10—157
Copper—Beryllium-copper shorts for electronic oscillators formed four times faster. C. S. Selby ..... Feb. 1— 97
Corrosion—How to control corrosion. C. D. Emerson (report) ..... Dec. 6—145-160

Costs:

Air-tools save $20,000 a month at Ryan Aeron ..... Mar. 15—153
Better think it over, Mr. Reuther! (ed) ..... Dec. 6—127
Cut costs with die-shim perforators. J. G. Schlindwein ..... Sept. 27—123
Electrostatic air cleaner saves oil, heat and money ..... Mar. 1—112
Get your special machines off to a good start—design and construction at Delco-Remy. C. A. Nichols ..... Feb. 15—121
Good tooling plus dial feeds will cut stamping costs. W. W. Schug .. Oct. 11—129
Is shell molding economical on job lots? F. K. Shallenberger (table) .. Oct. 25—130
Labor costs in small shops conserved by automation. J. B. Cunningham (report) (charts) ..... Apr. 12—177-184
Little dies lick big costs in short-run plastics. Edward Douglas ... Sept. 27—124
Offshore procurement: US purse strings are tightening ..... June 21—174
Perpetual motion is a key to production economics at Bendix Aviation ..... Oct. 25—122
Photographing tooling setups saves time and money. H. J. Friedman .. Dec. 6—134
Press-replacement study pays off for spring maker. J. R. Nikolais Dec. 20—130
Process evaluation pays long-term dividends. W. M. Stocker, Jr. (report) ..... June 21—133-140
Spin re-entrant shapes—low-cost method with low-melting alloys. Sams & Borodavchuk ..... Feb. 15—145
Spring-clean your business (ed) Apr. 12—159
Tool cost cut is 59% with Kendex tooling ..... Nov. 22—146
Toolroom time standards save labor costs. R. M. Crossan (tables). Sept. 27—113
Watch jig operating costs. W. J. Kokoskin (Ref. Bk. Sheets) Pts. 1 & 2 ..... Feb. 15—173
What regularized replacement can do (ed) ..... Apr. 26— 99

Cranes—Bicycle sprockets help small crane move freely. B. Goldrath (P.I.) .. June 7—158

In-place-machined pivot pin saves down-time of crane. Peter Cervelli (P.I.) ..... Apr. 26—138

Curves — Difference curves solve form-tool corrections. Oliver Saari (Ref. Bk. Sheets) (charts & tables) Pts. 1, 2 & 3 ..... Mar. 15—171

Cutters and Cutting Machines:

Brass lifter aids undercutting in planer. R. K. Edwards (P.I.) ..... Mar. 15—168
Cam feed speeds undercutting on 75-mm shell. S. F. Pasternak ..... Apr. 26—110
Carbide bur "grinds" radius slot on hardened 8713 steel. E. J. Tangerman (charts) ..... Apr. 12—172
Carbide cuts carbide chipbreakers when Watertown Arsenal applies electrical-discharge machining. Anderson Ashburn (charts) ..... Apr. 12—185
Centering a keyseat cutter. F. Moser (P.I.) ..... Apr. 26—138
Chart for threading time. T. Hicks (Ref. Bk. Sheets) ..... Mar. 1—135
Chip breaker balanced design—report. E. K. Henriksen (charts & tables) ..... Apr. 26—118
COs concept machines titanium alloys and heat-resistant materials. G. H. DeGroat ..... Aug. 2—152
Contact ratios for undercut gear teeth. Oliver Saari (Ref. Bk. Sheets) (charts) Pts. 1 & 2 ..... Jan. 18—269
Curved slots are drilled and cut in a timesaving method. H. P. Kunkleman ..... Aug. 2—110
Densified wood cut with jigs and rigs ..... Nov. 22—147
Easily constructed flycutter. John McCafferty (P.I.) ..... Aug. 2—140
Fixture sharpens milling cutters on lathe (P.I.) ..... Aug. 2—137
'Flying stop' shows drill cutting action. C. J. Oxford, Jr. ..... Mar. 1—102
Form cutters for helical gears. Oliver Saari (Ref. Bk. Sheets) (charts) Pt. 1 & 2 ..... Feb. 1—131
Form tools improved by compensated angles. R. G. Vare (P.I.) Apr. 12—215
Formula aids cutting double lead threads. H. W. Holmdahl (P.I.) ..... Jan. 4—117

(ed) Editorial (P.I.) Practical Ideas

Gear-cutting savvy in 16 easy steps. R. S. Hildreth ..... Mar. 29— 99
High-speed trepanning at Bethlehem Steel. W. M. Stocker, Jr. (report) ..... Jan. 4—105-114
How to estimate single-point cutting forces ..... Mar. 15—152
How to machine acrylic plastics. Dr. O. L. Pierson (report) (tables) ..... Feb. 1—113-120
Improvised "slotting machine" speeds work on plates. Clifford Molloy (P.I.) ..... May 10—176
Kick-press speeds rivet-cutting. S. Wencek (P.I.) ..... June 7—157
Machine-tool dynamometers . . . a current appraisal. Cook, Loewen & Shaw ..... May 10—125
Nomograph aids solution of worm-thread profiles. O. Saari (charts & tables) ..... July 5—113
Normal thread angles and bottom flats (Acme) Donals Sweet (tables) (Ref. Bk. Sheet) Pts. 1 & 2 ..... Sept. 27—147
Offset turning relieves form cutters. Henry George (P.I.) ..... Oct. 25—160
Pivoted cutter forms oil grooves. J. E. Bittern ..... Feb. 15—166
Rotating flycutter mills spheres with single-point tool. Louis Saiia (P.I.) ..... Apr. 26—136
Rotating guide-block aids taper cut. S. Hahne (P.I.) ..... Aug. 2—138
Russian design for cutting edge of single-point tools. Frank Sachs (charts) ..... Apr. 12—170
Russian report — ceramic-tipped tools will cut steel ..... Nov. 22—113
Screw machines speed stock cutting. Henry George (P.I.) ..... Jan. 4—120
Simple tailstock attachment aids aluminum tube cutoff. H. Koslow (P.I.) ..... May 10—175
Slicing knives help cut soft rubber roll. M. Barash (P.I.) ..... Oct. 25—161
Slotting-cutter runout. D. E. Sweet (chart) (Ref. Bk. Sheet) ..... Sept. 27—151
Special cutting heads finish 1066 hole. Carl Jensen (P.I.) ..... May 10—173
Standard milling cutter forms large radius. Henry George (P.I.) ..... Feb. 1—126
Thermal number measures efficiency of metal cutting. K. J. Trigger (report) (charts) ..... June 7—145-152
Threaded arbor saves straddle-mill set-up time. Henry George (P.I.) Apr. 26—138
Tool steel milling inserts machine valve faces. Carl Jensen (P.I.) ..... Dec. 20—119
Toolholder aids cutting of oil grooves. Clifford Molloy (P.I.) ..... Apr. 12—216
Trepan bottoming holes in one operation. R. W. Holmes ..... Aug. 16—120
Trepanning titanium saves time and material. Siemen & Rosato ..... Aug. 30— 89
Tubing cutoff method. A. I. Levitt (P.I.) ..... Aug. 16—148
Two blade cutoff tool. H. J. Gerber (P.I.) ..... Dec. 20—120
Ultrasonic machining (cover) ..... Aug. 30— 2
Washer cutter forms emergency belts. William Adams (P.I.) ..... Jan. 4—119
Wound-up form tool unwinds to cut contours. C. Molloy (P.I.) ..... Feb. 15—164

Cutting Fluids:

American Machinist production nuggets of machining ..... Mid-Nov. B1-37
CO_2 concept machines titanium alloys and heat-resistant materials. G. H. DeGroat ..... Aug. 2—152
Cool tips . . . not chip, with CO_2—new English technique ..... Feb. 15—130
Cures bad tap breakage or poor reaming finishes. Gus Wernberg (P.I.) ..... Mar. 15—167
Foam-cooling method increases tool life and improves work conditions. Mason & Weber (chart) ..... Apr. 12—174
High-speed trepanning at Bethlehem Steel., W. M. Stocker, Jr. (report). Jan. 4—105-114
Jet cooling triples feed rate on plunge and thread grinding of tool steel Rc62-64 (charts) ..... Jan. 4—137
Machining titanium with coolants (Ref. Bk. Sheets) (charts & tables) Pts. 1, 2 & 3 ..... May 24—155
Mist cooling goes to work Pt. 1 Thuma & Sdano. Pt. 2 Feuerpfeil, Titus & Thuerwach ..... Aug. 2—117-132
New look at cutting fluids. H. N. Leave ..... Mar. 1— 97
"Snorkel" cools deep tapping job. Robert Bryant (P.I.) ..... Oct. 25—161
Water treatment kills coolant bacteria ..... Mar. 29—145

Cutting Tool Mfrs. Assn.—Meeting. Mar. 1—140

Cylinders:

Cam-operated air cylinder for rapid part ejection. G. J. Bowman (P.I.) Feb. 1—124
Cylinder heads re-bored with nearly automatic machine ..... Apr. 12—250
Large cylinders of titanium alloy can be produced by trepanning from solid billets. Siemen & Rosato ..... Aug. 30— 89
Limits and fits for cylindrical parts (Ref. Bk. Sheets) Pts. 1, 2 & 3 July 19—151; Pts. 4, 5 & 6 Aug. 2—143; Pts. 7, 8 & 9 Aug. 16—151; Pts. 10 & 11 ..... Aug. 30 —19
Methods of grinding cylindrical parts (Ref. Bk. Sheets) Pts. 1 & 2 ..... Mar. 1—131
Soft iron cylinder holds end mill. I. R. Choudhary (P.I.) ..... Feb. 1—128

D

Deburring—Automatic brushing deburrs turbine disks. DePastina & Eyre July 5—124
"Plaster cast" solves tough deburring problem. Harold Rhodenbaugh (P.I.) ..... May 24—149

Defense:

An "ace" insurance policy (ed) ..... May 24—111
Chrysler—Run Michoud tank plant is largest to go standby ..... Sept. 13—198
Defense materials system simplified ..... Apr. 12—260
Guided missiles: is technical cloak-and-daggerism hiding a snafu? ..... July 5—162
Joint Congressional Committee report on defense production ..... Dec. 6—195
New orders for military hard goods ..... Oct. 25—182
Offshore ammunition procurement for Nato at the expense of US producers ..... Aug. 30—132
Product-market diversification in the event of defense requirements. A. H. Jones ..... Aug. 16—130
Senate blasts US Defense buying British aircraft ..... Aug. 16—160
TASA goes to Washington to get government recognition of aircraft in national defense ..... July 5—163
U.S. guided missile program ..... Mar. 1—138
Used machinery: second line of industrial defense? ..... May 24—170

Depreciation:

How the new U.S. tax laws affect metalworking (charts) ..... Sept. 13—194
New Englanders talk replacement ..... May 10—194
New tax laws: after 20 years U.S. business gets a break on depreciation ..... Aug. 16—158
Realistic depreciation rates. Burnham Finney (report) (chart) ..... Mar. 1—113-120
The remedy is not strong enough (ed) ..... Jan. 18—119
What are you doing about depreciation? (ed) ..... Sept. 27—111

Design:

Chip breaker balanced design. E. K. Henriksen (report) (charts & tables) ..... Apr. 26—118
Cope talks on draw dies. S. R. Cope
Pt. 8 Wide-flanged shells draw easily if you follow the rules ..... Jan. 4—100
Pt. 9 Know the wrinkles about spherical shells ..... Feb. 15—148
Pt. 10 Reverse drawing gives you greater reductions ..... Mar. 15—134
Pt. 11 Observe 6 rules when making tapered shells ..... Apr. 26—114
Pt. 12 Tapered shells require skillful operation layout ..... May 10—168
Pt. 13 Iron shells to get accurate diameters or smooth finish ..... June 7—134
Pt. 14 Three shell jobs typify ironing operations ..... July 5—126
Pt. 15 Necked shells require careful reduction ..... July 19—130
Pt. 16 Make offsets in dies or on lathes ..... Aug. 2—134
Pt. 17 Choose from 4 methods to bulge shells ..... Aug. 16—122
Pt. 18 Fluid dies bulge shells and form ornamental design ..... Aug. 30—109
Pt. 19 Stampings often require burred or flanged holes ..... Sept. 13—140
Pt. 20 Choice of die type depends on the burr ..... Sept. 27—120
Pt. 21 Three kinds of burrs require different dies ..... Dec. 6—166
Pt. 22 Make small shells in progressive dies ..... Dec. 20— 94
Diamond pin design. W. Paul Wing (Ref. Bk. Sheet) (chart & table) ..... Mar. 29—137
Get your special machines off to a good start—design and construction at Delco-Remy. C. A. Nichols ..... Feb. 15—121
New British designs in planes and in sport cars ..... Sept. 27—161
Novel gaging and design change in making governor weights saves money for Westinghouse. C. M. Modd ..... Feb. 1—103
Russian design for cutting edge of single-point tools. Frank Sachs (charts) ..... Apr. 12—170
Tool design checker. C. Bossman. Oct. 11—140

Diamonds, Industrial:

Electrolytically-assisted carbide grinding cuts diamond consumption. Thibault & Anderson (tables) ..... Feb. 15—154
Salvage of diamond sludge ..... Aug. 16—121
Shorter chipbreakers save diamonds. W. A. Fanger ..... May 24—113

Dies:

Adapter releases tubing die. William Hartmann (P.I.) ..... Dec. 20—116
Alcoa's bandsaw (cover) ..... Dec. 6— 2
Artists sculpture mica dies. J. P. Wright (charts & tables) (report) ..... Sept. 13—145-160
Bending die, redesigned, cuts one operation. H. Dahl (P.I.) ..... Jan. 4—119
Cam-operated air cylinder for rapid part ejection. G. J. Bowman (P.I.) ..... Feb. 1—124
Circular helix formed in one die operation. John Muth (P.I.) ..... Mar. 29—128
Cleaning die teeth. M. Barash (P.I.) ..... Dec. 20—119
Clearance between a punch and die. Don R. King (Ref. Bk. Sheets) Pts. 1 & 2 ..... Apr. 12—243
Comparator easily made from a commercial dieset. Jerry Coates (P.I.) ..... Oct. 11—175
Cope talks on draw dies. S. R. Cope
Pt. 8 Wide-flanged shells draw easily if you follow the rules ..... Jan. 4—100
Pt. 9 Know the wrinkles about spherical shells ..... Feb. 15—148
Pt. 10 Reverse drawing gives you greater reductions ..... Mar. 15—134
Pt. 11 Observe 6 rules when making tapered shells ..... Apr. 26—114
Pt. 12 Tapered shells require skillful operation layout ..... May 10—168
Pt. 13 Iron shells to get accurate diameters or smooth finish ..... June 7—134
Pt. 14 Three shell jobs typify ironing operations ..... July 5—126
Pt. 15 Necked shells require careful reduction ..... July 19—130
Pt. 16 Make offsets in dies or on lathes ..... Aug. 2—134
Pt. 17 Choose from 4 methods to bulge shells ..... Aug. 16—122
Pt. 18 Fluid dies bulge shells and form ornamental design ..... Aug. 30—109
Pt. 19 Stampings often require burred or flanged holes ..... Sept. 13—140
Pt. 20 Choice of die type depends on the burr ..... Sept. 27—120
Pt. 21 Three kinds of burrs require different dies ..... Dec. 6—166
Pt. 22 Make small shells in progressive dies ..... Dec. 20— 94
Die-setters manual. E. P. Boehnlein (Ref. Bk. Sheets) Pts. 1, 2 & 3 Nov. 8—167; Pt. 4 ..... Nov. 22—155
Dieset "take-apart" cart saves time, cuts die damage. J. G. Schlindwein ..... Mar. 1—110
"Duplicator" eases die layout. H. J. Gerber (P.I.) ..... Nov. 22—151
Electrical-discharge machining. Harding, Matulaitis & Stoke (report) ..... Mar. 15—137-148
Five-station progressive die forms and cuts off caps. S. E. Olson (P.I.) ..... June 7—159
Formulas for adjacent triangles. J. R. Paquin (Ref. Bk. Sheet) ..... Jan. 18—267
Hard bronze inserts for drawing and forming stainless dies without scratches. Arnold Walz ..... Aug. 2—106
Hardened guides eject slug problem. J. G. Schlindwein (P.I.) ..... Mar. 15—163
How Rohr heats dies to form titanium. J. E. Rheim ..... Oct. 11—161
How to machine acrylic plastics. Dr. O. L. Pierson (report) (tables) ..... Feb. 1—113-120
Little dies lick big costs in short-run plastics. Edward Douglas ..... Sept. 27—124
Magazine feed speeds second die operations. Federico Strasser (P.I.) ..... Mar. 15—165
Polished dies necessary in working tantalum and columbium. J. W. Rose (report) (charts & tables) ..... Apr. 12—189
Progressive die for lock-washer strip-stock fed through stripper. Hjalmar Dahl (P.I.) ..... Aug. 2—140
Rotating die trims silicon-steel strip on the bias. L. W. Tiefel ..... Oct. 11—139
Rotating toolholder shapes die openings. Henry Gifford (P.I.) ..... Mar. 1—126
Russians harness plastic mass for actuating medium ..... June 21—126
Self-opening dieheads cut threading time. W. D. Arnot (P.I.) ..... July 5—151
Side cams on assembly die speed switch assembly. Federico Strasser (P.I.) ..... Aug. 16—145

(ed) Editorial (P.I.) Practical Ideas

Sift die and hard arbor taper tubes. F. E. Chase (P.I.) ..... Sept. 27—141
Simple die change cuts springback. P. V. Dunn (P.I.) ..... Apr. 26—137
Simple wire-bending die. Federico Strasser (P.I.) ..... June 21—147
Soft dowels in hard dies simplify die assembly. P. V. Dunn (P.I.) Mar. 29—130
Sound tooling simplifies tough progressive die. James Brown ... Nov. 22—143
Split spring-steel retaining ring gives close die stripping. N. Schwartz (P.I.) Dec. 6—172
Springback eliminated with another simple die change. P. V. Dunn (P.I.) July 19—146
Square-end cutoff die. C. E. Whitcomb (P.I.) ..... Feb. 1—128
Stripping shell from dies by coil spring. Burnett Menkin (P.I.) Apr. 12—213
Tapered shims aid grinding dies clearances. A. Jonas (P.I.) ..... Oct. 11—176
Thin-lead plate measures die-opening dimensions. Erik Roed (P.I.) May 24—150
Threading die repair. F. Strasser (P.I.) Dec. 20—120
Versatile producer . . . the press brake. J. M. Matthewman
Pt. 2 Piercing and notching units permit progressive setups Jan. 4— 96
Pt. 3 Think of press brakes beyond the first job ..... Feb. 1—108
Work cuts tool, tools forms work . . . with ultrasonics. E. J. Tangerman Aug. 30— 85
Difference curves—Solve form-tool corrections. Oliver Saari (Ref. Bk. Sheets) (charts & tables). Pts. 1, 2 & 3 Mar. 15—171
Dovetails—Gaging method eases making dovetail form tools. E. Quinn (P.I.) Dec. 6—172
Plug constants for checking dovetails. Donald Sweet (Ref. Bk. Sheets) (tables) ..... Aug. 30—123

Drawing:

Cope talks on draw dies. S. R. Cope
Pt. 8 Wide flanged shells draw easily if you follow the rules ... Jan. 4—100
Pt. 9 Know the wrinkles about spherical shells ..... Feb. 15—148
Pt. 10 Reverse drawing gives you greater reductions ..... Mar. 15—134
Pt. 11 Observe 6 rules when making tapered shells ..... Apr. 26—114
Pt. 12 Tapered shells require skillful operation layout ..... May 10—168
Pt. 13 Iron shells to get accurate diameters or smooth finish ... June 7—134
Pt. 14 Three shell jobs typify ironing operations ..... July 5—126
Pt. 15 Necked shells require careful reduction ..... July 19—130
Pt. 16 Make offsets in dies or on lathes ..... Aug. 2—134
Pt. 17 Choose from 4 methods to bulge shells ..... Aug. 16—122
Pt. 18 Fluid dies bulge shells and form ornamental design ... Aug. 30—109
Pt. 21 Three kinds of burrs require different dies ..... Dec. 6—166
Pt. 22 Make small shells in progressive dies ..... Dec. 20— 94
Deep drawing chow tubs for the Navy Sept. 27—160
Hard bronze inserts for drawing and forming stainless dies without scratches. Arnold Walz ..... Aug. 2—106

Dressers—Crush-dress grinding wheels for parts of plastic and wood rod. Gentile & Schaper ..... May 10—134

Drills and Drilling:

Air motor in tailstock adds to small-drill speed. J. T. Zurlo (P.I.) ..... Sept. 27—143
American Machinist production nuggets of machining (charts & tables) .... Mid-Nov.—B1-37
Bandsaw welder butt-welds small drill extensions. Joseph Mate (P.I.) May 10—174
Cartridge units for adjustable drillhead. Henry Gifford (P.I.) ..... Aug. 16—148
Conversion capers speed threading and drilling. A. G. Gould ..... Dec. 20—109
Curved slots are drilled and cut in a timesaving method. H. P. Kunkleman Aug. 2—110
Double V-gage centers drills to drill round stock. H. J. Gerber (P.I.) ... Mar. 15—167
Drill units move tools to work, not work to tools. C. A. Wiken May 24—122
Drillpress fixture speeds second operation. Edward Schmidt (P.I.) Apr. 12—214
Drillpress for turning small punches from ground rod. C. B. Winch (P.I.) Sept. 27—143
Eccentric-driven, gearless multiple-drill head. Fred Lawrence (P.I.) Feb. 1—127
Eccentric-driven gearless multiple drill-head. E. B. Olson (P.I.) Mar. 1—127
Extensions added to drillheads speed plate-drilling. H. George (P.I.) ... June 7—160
Fixture for milling flats on drills. Edward Schmidt (P.I.) ..... Aug. 30—114
'Flying stop' shows drill cutting action. C. J. Oxford, Jr. ..... Mar. 1—102
Form tool drills dozen 0.013-in. holes. G. W. Roderick (P.I.) ..... July 19—145
Honing to 1 mu in. on a radial (cover) Dec. 20— 2
H-beam supports yokes for easy drilling. A. V. Hogg (P.I.) ..... Mar. 1—127
Interchangeable templets diversify drill jig. L. H. Austin (P.I.) ... Mar. 1—128
Jack removes arbors from drill chucks Henry George (P.I.) ..... Mar. 1—128
Length of drills (Ref. Bk. Sheets) (chart) ..... Oct. 11—183
Mist cooling goes to work (report) Pt. 1 Thuma & Sdano; Pt. 2 Feuerpfeil, Titus & Thuerwach ... Aug. 2—117-132
New drill angles for titanium from Republic Aviation ..... June 21—142
New uses for trunnion fixtures on your radials ..... Apr. 26—112
Powered drillpress table speeds deep-hole work. Charles Fry (P.I.) Sept. 13—182
Radial drill graduates table. W. J. Green (P.I.) ..... June 21—146
Radial drills make chips by the ton. Leo Braun ..... May 24—148
Removing broken drills and taps. L. R. Choudhary (P.I.) ..... Jan. 4—116
Rotating gun drill cancels secondary operations ..... Aug. 16—162
Sandwich helps drill semicircular holes. F. Mernieks (P.I.) ..... Mar. 1—125
Screw-machine converted for gun-drilling. W. M. Stocker, Jr. ... Feb. 15—162
Serrated depth-stop speeds stainless drilling. F. H. Sumption (P.I.) Oct. 11—176
Side-drilling in turret lathe drills work in place. M. Yamaguchi (P.I.) Feb. 1—125
Six-station drillpress speeds single-spindle work. Clifford Molloy (P.I.) Apr. 12—140
Soft touch for small-hole drilling. J. P. Steibel ..... Sept. 13—138
Spring-and-V-block fixture aids drilling small shafts. M. Barash (P.I.) ... May 10—175
Tolerances for tap-drill holes (tables) (Ref. Bk. Sheets) Pts. 1, 2 & 3 Apr. 26—143

Drives:

Ball-bearing telescoping drive. M. L. Parsons (P.I.) ..... Aug. 30—114
Ball-bearing tube-driver for rough ID, finished OD. A. Fischer (P.I.) ... Feb. 15—165
Work-driving without a dog. H. J. Gerber (P.I.) ..... Oct. 25—163
Dust collectors—Electrostatic air cleaner saves oil, heat and money ... Mar. 1—112
Dynamometers—Current appraisal of machine-tool dynamometers. Cook, Loewen & Shaw ..... May 10—125

E

Ejectors:

Cam-operated air cylinder for rapid part ejection. G. J. Bowman (P.I.) Feb. 1—124
Double-acting pressure pad aids part ejection. G. J. Bowman (P.I.) Jan. 4—117
Hardened guides eject slug problem. J. G. Schlindwein (P.I.) Mar. 15—163
Hush up your ejector racket. J. G. Schlindwein ..... Sept. 13—180

Electrical connections—Production methods are key to improved belt design. M. Brerrer ..... July 5—146
Electrical-discharge machining. Harding, Matulaitis & Stoke (report) Mar. 15—137-148
Electrical-discharge machining applied at Watertown Arsenal. Anderson Ashburn (charts) ..... Apr. 12—185

Electronics:

Automatic assembly of complex electronic assemblies ..... Mar. 15—186
Automatic machine control for job-lot production seen as outgrowth of GE electronic system ..... Feb. 15—182
"Dividing-head" device checks complex electronic parts. Walter Yeager, Sr. (P.I.) ..... May 10—176
Electron plumbing . . . tricks in making. C. S. Selby ..... Feb. 15—134
Numerical control, what it means to metalworking. Stocker, Jr. & Emerson (table) (report) Oct. 25—133—156
Second industrial revolution?—automation of electronics ..... May 10—190
Sound-color film available on free loan to industry ..... July 5—164
UHF contacts for electronic oscillators formed four times faster. C. S. Selby Feb. 1— 97

Ellipses—Formula for ellipse layout. W. J. Stedman (P.I.) ..... July 5—152

(ed) Editorial (P.I.) Practical Ideas

Engineers—Airborne Instrument Laboratory—program to make your own engineers. H. J. Gresens ..... Feb. 15—127

Engines:

Continental Motors production shortcuts help power tanks. G. H. DeGroat July 19—122
Cylinder assemblies speed up diesel production ..... Mar. 29—108
Hot-extruded aluminum pistons. May 10—172
How Britain machines big diesel crankshafts ..... Mar. 15—158
Steam engines—1907 and 1954 .. Mar. 1—140

Equipment—American Machinist production nuggets of materials handling and plant service ..... Mid-Nov. 11— 17
Trade with Russia—once banned metal-working equipment can be shipped. Sept. 13—198

Estimating — How to estimate single-point cutting forces. W. L. Kennicott. Mar. 15—152
European Machine Tool Exhibition—Milan Fair 1954 ..... Oct. 11—186

Exports:

British machine tools: export business is good ..... Aug. 2—156
East-West embargo eases: what and where can Russia buy now? Aug. 16—165
Foreign aid to boost US production and trade ..... Sept. 27—154
Less-developed countries potential market for US exports ..... Oct. 11—189
On behalf of more exports (ed). July 19—115
Trade with Russia—once banned metal-working equipment can be exported. Sept. 13—198

Extrusion:

Beryllium billets must be "canned" for extrusion. Lowenstein, Kaufman & Arnold (report) ..... Apr. 12—203
Cold-extruding rocket noses ... May 24—169
Hot-extruded aulminum pistons. May 10—172
Hot extruding aluminum fan blades to 0.001-in. tolerance in 1100-ton press. Feb. 15—184
Hot extrusion of steel and titanium shapes ..... Apr. 12—256
Special tools support 14,000-ton extrusion press. W. C. Winter (table) Dec. 6—162

Eye glasses — Will 100% safety glasses work? ..... Oct. 25—123

F

Fasteners—Aircraft designers replace heavy metal fittings and fasteners with titanium ..... Aug. 30—128

Feeds:

Cam feed speeds undercutting on 75-mm shell. S. F. Pasternak ..... Apr. 26—110
Good tooling plus dial feeds will cut stamping costs. W. W. Schug. Oct. 11—129
Magazine feed speeds second die operation. Federico Strasser (P.I.) Mar. 15—165
Solenoid stops VTL ram feed. J. K. Gensler (P.I.) ..... July 19—147
Speeds and feeds for turning steel. (Ref. Bk. Sheet) (charts) ... Dec. 6—183

Files—Chalk aids filing. R. Isetts (P.I.) Mar. 15—167

Financial:

An "ace" insurance policy (ed). May 24—111
Foreign aid: the trend is toward making it a US business aid, too. Sept. 27—154
Gisholt adds extended payment plan to leasing setup ..... Nov. 22—165
"Most flexible finance-leasing plan" in the machine-tool field offered by Jones & Lamson and CIT ..... Aug. 2—158
New plants and equipment 1955-56 (table) ..... Nov. 8—174
Offshore procurement: US purse strings are tightening ..... June 21—174
Progress payments ease off ... May 10—193
Small business loans: the red tape is cut ..... July 19—165
Vance Plan—First it's in, then out—now it's back, but smaller July 19—161
What the public will spend in '54. Mar. 29—143

Finishing:

American Machinist production nuggets of heat treating, cleaning, finishing (table) ..... Mid-Nov. G1— 7
Automatic brushing deburrs turbine disks. DePastina & Eyre ... July 5—124
Barrel finishing . . . more art than science. Leonard Giglio ... Mar. 15—125
Belt finishing of carbide tools proves effective. F. J. Lennon Jr. .. Feb. 1—104
Electrical-discharge machining. Harding, Matualitis & Stoke (report) Mar. 15—137-148

How to choose power brushes. R. O. Peterson (charts) (Ref. Bk. Sheets) Pts. 1, 2 & 3 ..... Oct. 25—167
Machining porous powder-metal parts. Langhammer & Glick (charts) Apr. 26—101
Stretch aluminum plate to reduce machining distortion. Lawler & Binkley (tables) ..... Mar. 15—128
Toolpost-mounted air sander burnishes hydraulic ram. J. T. Zurlo (P.I.) ..... June 21—146
Vertical boring mill designed to finish interior surfaces of casing for jet engines (cover) ..... Apr. 26— 2
Fire protection—Why production-wise, plant-protection foolish? W. K. Ousley. ..... May 24—146
Floturn—New concept in plastic deformation, saves operations and conserves materials. C. L. Sporck ..... May 29—104
New metalworking process (cover). ..... Mar. 29— 2
Foremen—Supervisors for tomorrow. Wm. M. Stocker Jr. (report)...Aug. 16—133-140

Forgings:

Beryllium requires special forging methods. S. M. Bishop (report)...Apr. 12—207
Hand vs. machine (cover)... Oct. 25— 2
How Britain machines big diesel crankshafts ..... Mar. 15—158
Modern planes from hand forging. ..... Sept. 27—157
Pick-a-back tooling machines forgings for giant press. W. M. Stocker, Jr. ..... July 19—117
Saugus Iron Works: our industrial heritage returns to life..... Sept. 27—159
Test forging 5000-lb. ingots for AF heavy presses ..... July 19—164
USSR induction forges replaces hammers ..... Aug. 30—130

Forming:

Annealing and hot working of metals. Samuel Storchheim (charts & tables) (report) ..... Sept. 13—161-168
Big stretch press goes in (cover). ..... Aug. 16— 2
Circular form-tool corrections. I. Zorich (Ref. Bk.. Sheets) ..... Mar. 29—135
Cold-forming gears and splines. June 21—169
Corrections for flat form tools. I. Zorich (Ref. Bk. Sheets) (charts) Mar. 29—133
Corrugation-forming speeded by adjustable rollers. H. Dahl (P.I.). June 7—159
Difference curves solve form-tool corrections. Oliver Saari (Ref. Bk. Sheets) (charts & tables) Pts. 1, 2 & 3. ..... Mar. 15—171
Form tools improved by compensated angles. R. G. Vare (P.I.) Apr. 12—215
Hand forming—machine style. N. L. Whipple ..... Nov. 22—141
Hard bronze inserts for drawing and forming stainless dies without scratches. Arnold Walz ..... Aug. 2—106
High-pressure forming press for jet planemaking operations Sept. 27—158
How Ryan forms and welds titanium ..... Dec. 6—138
How to choose hydraulic presses for metal forming operations. H. D. Thweatt (report) ..... Mar. 29—115-126
How to form integrally stiffened skins. W. T Kluge (report) Nov. 22—129-140
How to stretch-form aluminum. J. M. Adle (report) ..... July 19—133-140
Production methods are key to improved boat design. M. Brenner ..... July 5—146
Roll flowing saves operations and conserves material in plastic deformation. C. L. Sporck ..... Mar. 29—104
Simple die change cuts springback. P. V. Dunn (P.I.) ..... Apr 26—137
Stepped "gage table" aids form grinding. Frank Geiger (P.I.) Apr. 26—139
UHF contacts formed four times faster. C. S. Selby ..... Feb. 1— 97
Wound-up form tool unwinds to cut contours. C. Molloy (P.I.) Feb. 15—164
Furnaces—Convair's solar furnace helps materials break the thermal barrier ..... May 10—192

G

Gages and Gaging:

Adjustable gages. A. G. Amos (P.I.) ..... Sept. 27—141
Adjustable scriber simplifies vernier height gage settings. R. H. Fry (P.I.) ..... Aug. 16—147
Center positioning gage for angular wheel-truing. H. J. Gerber (P.I.) ..... Mar. 1—127
Concentricity check aided by coated wheel on V-block. Cliff Bossman (P.I.) ..... May 24—150
Dodge gages V-8 bores in the machine shop. R. S. MacPhail ..... Oct. 11—134
Double V-gage centers drills to drill round stock. H. J. Gerber (P.I.)... Mar. 15—167
Guided rings check tapers. W. I. Morgan (P.I.) ..... Mar. 29—129
How the first "jo" block was measured ..... Apr. 12—255
How U.S. Navy probes bores. J. A. Penn ..... Mar. 15—160
Inexpensive gage helps match tapers. Carl Jensen (P.I.) ..... Feb. 1—124
Limit switches gage centers in high production. J. W. Farrell (P.I.) ..... Nov. 22—151
Long gaging job (cover)..... May 24— 2
Method eases making dovetail form tools. E. Quinn (P.I.) ..... Dec. 6—172
Novel gaging and design change in making governor weights saves money for Westinghouse. C. M. Modd Feb. 1—103
Precision limit switches for production gaging. S. Kopacz (P.I.) ..... May 24—152
Simple device gages vise-held work. Jaan Wain (P.I.)..... Oct. 25—164
Simple gage measures large radius. A. C. Charracharya (P. I)...Dec. 6—174
Stepped "gage table" aids form grinding. Frank Geiger (P.I.) Apr. 26—139
Tension for press setup checked with gage bar. A. Vetsch (P.I.)....Feb. 1—127

Gears and Gearing:

American Gear Manufacturers Assn. meeting ..... June 21—170
American Gear Mfrs. Assn. announces new gear standards..... Nov. 8—182
American Machinist production nuggets of machining (charts & tables)..... Mid-Nov.—B1-37
Calculations of "metal-to-metal" involute gears. Oliver Saari..... Dec. 20— 89
Cold-forming gears and splines June 21—169
Contact ratios for undercut gear teeth. Oliver Saari (charts) (Ref. Bk. Sheets) Pts. 1 & 2 ..... Jan. 18—269
Form cutters for helical gears. Oliver Saari (Ref. Bk. Sheets) (charts) Pts. 1 & 2 ..... Feb. 1—131
Form grinding helical-gear teeth. Oliver Saari (table) ..... Sept. 13—172
Gear-cutting savvy in 16 easy steps. R. S. Hildreth ..... Mar. 29— 99
Gear-hob tolerances. H. V. Gregg (Ref. Bk. Sheets) (tables) Pts. 1 & 2 ..... Nov. 22—157 Pts. 3 & 4 ..... Dec. 6—179
New look at wormgear hobbing. Ernest Wildhaber (report)..... June 21—149-152
Old gear makes dividing-head lathe. J. M. Heath (P.I.)..... Aug. 16—147
Selective hardening in a salt bath minimizes distortion. C. G. Lee ..... May 10—132
Shaper attachment generates bevel gears. Haim Murro ..... Mar. 1—122
Tests evaluate Wildhaber formulas... ..... July 5—166
Tooth-by-tooth induction hardening multiplies gear strength and life. C. A. Pethybridge (charts & tables)..Oct. 25—117

Germany:

Machine tools from Germany dominate Vienna Fair ..... May 24—164
Small output, high craftsmanship characterizes rear-engined Porsche Aug. 2—156
Volkswagen turns out 900 cars a day ..... Aug. 2—157
Great Britain—Machine tools business is good ..... Aug. 2—156

Grinders and Grinding Machines:

American Machinist production nuggets of machining (charts & tables)... ..... Mid-Nov.—B1-37
Auxiliary spring makes safer surface grinder. W. C. Betz (P.I.) Mar. 15—164
Belt grinding of titanium (Ref. Bk. Sheets) (charts) Pts. 1, 2 & 3. ..... June 7—163
Candle helps soft-metal grinding. Hugh Lineback (P.I.) ..... Oct. 25—162
Carbide bur "grinds" radius slot on hardened 8715 steel. E. J. Tangerman (charts) ..... Apr. 12—172
Caterpillar Tractor hollow-grinds clamped carbide tips. Matt Aljanich ..... Jan. 4— 89
Chemical reaction: the grinder's friend or foe? ..... Sept. 13—197
Contact wheels influence abrasive-belt performance. Dirck Olton....June 21—121
Cradle grinding makes abrasive belts more automatic ..... Feb. 15—153
Drillpress fixture speeds second operation. Edward Schmidt (P.I.) Apr. 12—214
Electrical-discharge machining. Harding, Matulaitis & Stoke (report) Mar. 15—137-148
Electrolytically-assisted carbide grinding cuts diamond consumption. Thibault & Anderson (tables)..Feb. 15—154
Finish grinding of carbide tools with abrasive belts proves effective. F. J. Lennon, Jr. ..... Feb. 1—104
Form tools improved by compensated angles. R. G. Vare (P.I.)... Apr. 12—215
How abrasive-belt grinding improves taper sheet production. J. R. Burns... ..... Nov. 22—126
How to centerless-grind parts of plastic and wood rod. Gentile & Schaper... ..... May 10—134
How to grind carbide-tipped tools (Ref. Bk. Sheet) ..... Dec. 20—125
Jet cooling triples feed rate on plunge and thread grinding of tool steel Rc62-64 (charts) ..... Jan. 4—137
Methods of grinding cylindrical parts (Ref. Bk. Sheets) Pts. 1 & 2.... ..... Mar. 1—131
Mounting cylindrical grinding wheels (Ref. Bk. Sheet) ..... Apr. 12—243
Non-cylindrical contours . . . how you can grind them. J. P. Wright (report) ..... May 10—137-156
Nomographic aids solution of worm-thread profiles. O. Saari (charts & tables) ..... July 5—113
Seismograph places grinders (chart)... ..... Apr. 12—209
Shaper doubles as surface grinder. Gurbachan Singh (P.I.)..... Dec. 6—173
Slotted toolholder makes offhand grinding safer. T. A. Fitzgerald (P.I.) ..... May 29—129
Sponge rubber solves grinding problem. Jack Finlay (P.I.) ..... July 19—146
Stepped "gage table" aids form grinding. Frank Geiger (P.I.) ...Apr. 26—139
Take your pick of a million grinding wheels. N. P. Robie (tables) Aug. 2—114
Titanium grinding no longer a problem. E. J. Krabacher (charts & tables).. ..... June 21—124
Vacuum chuck holds thin strip for grinding. Robert Weidenhoft (P.I.)..... ..... Sept. 27—142

Grooves and Grooving:

Ingenious holding method helps mill helical groove. A. Vetsch (P.I.). June 7—157
Oil grooves cut by double-toolholder. Clifford Molloy (P.I.)..... Apr. 12—216
Pivoted cutter forms oil grooves. J. E. Bittern (P.I.) ..... Feb. 15—166

H

Hammers:

Bicycle grip improves hammer. Fred Lettino (P.I.) ..... Feb. 1—124
Hammers for Skyrays (cover)..... July 5— 2
One-piece hammer and crank tightens milling vises. Henry Gifford (P.I.)... ..... Jan. 4—118
Riveting hammer drives nails to depth. G. Collinson (P.I.) ..... Jan. 4—118
Handles—Repairing worn file handles. William Adams (P.I.)..... Apr. 26—137

Hard Facing:

Gas-welding hard surfaces for precision. John Wischhusen ..... May 24—126
Gear distortion minimized by selective hardening in a salt bath. C. G. Lee ..... May 10—132
Lathe beds torch-hardened (cover) ..... Jan. 4— 2

Heat Treatment:

American Machinist production nuggets of heat treating, cleaning, finishing (tables) ..... Mid-Nov.—G1-7
Annealing and hot working of metals. Samuel Storchheim (charts & tables) (report) ..... Sept. 13—161-168
Boeing develops scale-inhibiting treatment for titanium and stainless... ..... Aug. 30—112
Convair's solar furnace helps materials break the thermal barrier... ..... May 10—192
Gas burners braze turbine blades. E. M. Mickley ..... Dec. 6—170
Gear distortion minimized by selective hardening in a salt bath. C. G. Lee ..... May 10—132
Hot extrusion of steel and titanium shapes ..... Apr. 12—256
Hot-spinning stainless (cover) Sept. 27— 2
How Rohr heats dies to form titanium. J. E. Rheim ..... Oct. 11—161
How to understand heat-treatment processes. Samuel Storchheim (charts) ..... Apr. 26—125
Thermal number measures efficiency of metal cutting. K. J. Trigger (report) (charts) ..... June 7—145-152
Titanium can be furnace-brazed. R. A. Long ..... Aug. 16—117
Tooth-by-tooth induction hardening multiplies gear strength and life. C. A. Pethybridge (charts & table)..Oct. 25—117

(ed) Editorial (P.I.) Practical Ideas

Helix—Circular helix formed in one die operation. John Muth (P.I.)....Mar. 29—128

Hobs and Hobbing:

Contact ratios for undercut gear teeth. Oliver Saari (Ref. Bk. Sheets) (charts) Pts.1 & 2.....Jan. 18—269
Gear-cutting savvy in 16 easy steps. R. S. Hildreth .....Mar. 29— 99
Gear-hob tolerances. H. V. Gregg (Ref. Bk. Sheets) (tables)
Pts. 1 & 2 .....Nov. 22—157
Pts. 3 & 4 .....Dec. 6—179
New look at wormgear hobbing. Ernest Wildhaber (report).....June 21—149-152

Holes:

Center holes pulverized in plastics. A. L. Levitt .....Oct. 11—144
Cope talks on draw dies. S. R. Cope. Pt. 19 Stampings often require burred or flanged holes .....Sept. 13—140
Copper "shim" opens tapped holes. Federico Strasser (P.I.).....May 10—173
Cut costs with die-shim perforators. J. G. Schlindwein .....Sept. 27—123
Drill angles for titanium from Republic Aviation .....June 21—142
Drilled plate aids layout of equidistant holes. J. M. Heath (P.I.).....May 24—151
Finish 1066 holes with special cutting head. Carl Jensen (P.I.).....May 10—173
Ford precision bores valve-stem holes (cover) .....Mar. 1— 2
Form tool "drills" dozen 0.013 in. holes. G. W. Roderick (P.I.).....July 19—145
High-speed trepanning at Bethlehem Steel. W. M. Stocker, Jr. (report) .....Jan. 4—105-114
Powered drillpress table speeds deep-hole work. Charles Fry (P.I.) Sept. 13—182
Rotating gun drill cancels secondary operations .....Aug. 16—162
Sandwich helps drill semicircular holes. F. Mernicks (P.I.) .....Mar. 1—125
Soft touch for small-hole drilling. J. P. Steibel .....Sept. 13—138
Trepan bottoming holes in one operation. R. W. Holmes .....Aug. 16—120
Tolerances for tap-drill holes (tables) (Ref. Bk. Sheets) Pts. 1, 2 & 3 .....Apr. 26—143
Hones and Honing—Honing to 1 mu in. on a radial (cover) .....Dec. 20— 2

Hydraulic Equipment:

How to choose hydraulic presses for metal forming operations. H. D. Thweatt (report) .....Mar. 29—115-126
Machine tool hydraulics—forum June 21—168
Small hydraulic presses do yeoman work. R. H. Behrend .....Oct. 25—126

I

Indexing—Mill square ends with indexing head. Irving Epstein (P.I.) ....Jan. 4—118

Indicators:

Carbide-tipped finger gages cutoff tubing lengths. Frank O'Connell (P.I.) .....Sept. 13—184
Contacts in fixtures assure repetitive accuracy. F. E. Piekos.....Oct. 11—136
Dial indicator helps find center of bore. John McCafferty (P.I.).....Sept. 13—183
Induction Heating—Tooth-by-tooth induction hardening multiplies gear strength and life. C. A. Pethybridge (charts & table) .....Oct. 25—117
USSR induction forges replace hammers .....Aug. 30—130
Industry Supply Convention—Supply groups hold joint meeting.....June 7—178
Ingersoll Milling Machine Co. modernization .....Apr. 26—154

Inspection:

American Machinist production nuggets of inspecting, testing, quality control .....Mid-Nov.—E1-5
Concentricity check aided by coated wheel on V-block. Cliff Bossman (P.I.) ... .May 24—150
"Dividing-head" device checks complex electronic parts. Walter Yeager, Sr. (P.I.) .....May 10—176
Exposing machine-tool gremlins with high-speed photography. L. C. Tullis (chart) .....June 7—156
Gage room in the middle of machining area permits close check on engine-bore dimension. B. S. MacPhail....Oct. 11—134
How to inspect carbide-tipped tools (Ref. Bk. Sheet) .....Dec. 20—127
Optical method of measuring alignment errors in micrometers. J. P. Wright (chart) .....Apr. 12—168
Plug constants for checking dovetails. Donald Sweet (Ref. Bk. Sheets) (tables) .....Aug. 30—123
"Sound locator" checks special machinery. I. Epstein (P.I.).....Feb. 15—167
US machine tool inspection completed .....Aug. 2—157

Instruments:

Machine-tool dynamometers—a current appraisal. Cook, Loewen & Shaw... .....May 10—125
Optical method of measuring alignment errors in micrometers. J. P. Wright (chart) .....Apr. 12—168
Production tools for precision from Ford Instrument. W. M. Stocker, Jr. .....June 21—117
Seismograph places grinders (chart)... .....Apr. 12—209
Inventory—3 colors from 1 inventory with pre-coated metal coil flashlight batteries .....Jan. 4—104
Iron—How to work iron and steel. Ashburn & Le Grand (charts & tables) (report) .....Mid-Nov.—33-160
Low-grade iron ores: Ford finds a way to use them .....July 5—167

J

Japan—Industry on the rebound... June 21—172

Jigs and Fixtures:

American Machinist production nuggets of tooling .....Mid-Nov.—C1-13
Automatic welding fixture eliminates need for costly positioning. Troyer & Lorain, Jr. (chart) .....Apr. 26—108
Ball-bearing fixture rolls out copper wire. M. Barash (P.I.).....Apr. 26—139
Ball-bearing locks on fixture aid turning of ordnance shells. D. G. Nolle (P.I.) .....May 24—152
Bench lathe fixture speeds capillary tube cutoff. G. S. Norko (P.I.)... Sept. 27—144
Coated wheel on V-blocks aids concentricity check. Cliff Bossman (P.I.) .....May 24—150
Contacts in fixtures assure repetitive accuracy. F. E. Piekos.....Oct. 11—136
Densified wood cut with jigs and rigs .....Nov. 22—147
Devices eliminate shear pins. W. C. Betz (P.I.) .....June 21—148
Drill jig cuts non-productive time when loading work. Federico Strasser (P.I.) .....Dec. 20—117
Drillpress fixture speeds second operation. Edward Schmidt (P.I.) .Apr. 12—214
Drillrod helps dowel removal. J. N. Schwartz (P.I.) .....June 7—158
Fixture for castings with wrong draft angle. Fred Dewick (P.I.)....Feb. 1—126
Fixture helps polish small-diameter pivots. Giroa Herzl (P.I.)...May 24—151
Fixture loads itself from conveyor (cover) .....Oct. 11— 2
45° mounting brakes locating ball versatile. C. Stougaard (P.I.).....June 7—158
Gang-cutters speed plug hexing. H. T. Green (P.I.) .....Sept. 27—144
Honeycomb fixture holds rings flat during quenching. E. Taylor (P.I.)... .....Aug. 16—146
Interchangeable templets diversify drill jig. L. H. Austin (P.I.)....Mar. 1—128
Internal "steadyrest" cuts boring bar chatter. H. J. Gerber (P.I.) June 21—147
Jig borers for juke boxes (cover) Feb. 1— 2
Jig borers in profusion (cover).. Aug. 2— 2
Lathe fixture sharpens milling cutters (P.I.) .....Aug. 2—137
Milling fixture for flats on drills. Edward Schmidt (P.I.) .....Aug. 30—114
New uses for trunnion fixtures on your radials .....Apr. 26—112
Planetary fixture mills flats in position in turret lathe. Robert Wiedenholt (P.I.) .....Mar. 15—166
Russians harness plastic mass for actuating medium .....June 21—126
Shaper attachment generates bevel gears. Haim Murro .....Mar. 1—122
Slots indicate fixture distortion. G. R. Milner (P.I.) .....Dec. 6—173
Spring-and-V-block fixture aids drilling small shafts. M. Barash (P.I.). .....May 10—175
Watch jig operating costs. W. J. Kokoskin (Ref. Bk. Sheets) Pts. 1 & 2 .....Feb. 15—173
Workholding devices handbook. H. E. Linsley (report) Pt. 2 Stationary devices .....Oct. 11—145-160

K

Knives—Slicing knives help cut soft rubber roll. M. Barash (P.I.) .....Oct. 25—161

Knurling:

Bench tool knurls piano wire. E. F. Siebold (P.I.) .....Aug. 2—139
"Centerless" knurling saves parts (P.I.) .....Mar. 29—127
Lightly cut screw thread simplifies knurling. M. Barash (P.I.)....Feb. 1—127

L

Labor:

Airborne Instruments Laboratory program to make your own engineers... .....Feb. 15—127
American Federation of Labor settles IAM and Carpenters Union disputes .....Oct. 11—190
American Machinist production nuggets of management, personnel (charts & tables) .....Mid-Nov.—A2-19
Are you a visual or a verbal man? J. J. Jehring .....Dec. 6—129
Better think it over, Mr. Reuther! (ed) .....Dec. 6—127
Co-determination (ed) .....Dec. 20— 87
Diemakers local split from the International Assn. of Machinists...Mar. 15—184
'54 wage hike pattern is taking shape .....July 5—164
Get returns from foreman training. G. S. Odiorne .....Dec. 6—137
How long can the cycle last? (ed) .....Oct. 25—115
How to pass the word. T. A. Jackson .....July 5—148
It's the people who count (ed)..Mar. 15—119
Mutual hiring saves headaches Feb. 1—121
Reuther's report on automation..Dec. 6—190
Shop canteen—Consolidated Engr. Corp. (cover) .....Feb. 15— 2
Shop thief. B. A. Hall.....Mar. 15—156
Suggestion plans—what makes them work? V. H. Rotroff .....July 19—144
Taft-Hartley's new look by reinterpretation of rules .....Aug. 30—126
Try pleasing your boss. E. J. Engle .....Apr. 26—105
Unemployment question in Detroit... .....Apr. 12—260
Wage incentive plans — put Standard Minute plan to work. K. L. Kline (chart & table) .....Mar. 1—106
Wage incentives cut production time 27% at Jones & Lamson. R. S. Jones .....May 24—118
Wakefield Brass practical "lab" tests light and quiet. C. A. Schroeder.. .....May 24—124
What the 50-plus club offers (ed) .....Mar. 29— 95

Laps and Lapping:

American Machinist production nuggets of machining .....Mid-Nov.—B1-37
Electron plumbing—some tricks in making. C. S. Selby .....Feb. 15—134
Sealing wax saves lapping job. Ralph Conklin .....Apr. 12—214

Lathes:

Adapter corrects turret misalignment. N. Feinberg (P.I.).....July 19—148
Adjustable toolblocks speed setups. A. G. Gould (P.I.).....Sept. 13—183
Automation combines standard lathes. E. J. Tangerman .....Mar. 29—110
Ball-bearing steadyrest cuts marking friction. R. W. Warner (P.I.) Mar. 15—168
Graduations speed steadyrest setup. Henry George (P.I.).....Feb. 15—167
Lathe beds torch-hardened (cover) Jan. 4— 2
Mist cooling goes to work. Pt. 1 Thuma & Sdano. Pt. 2 Feuerpfeil, Titus & Thuerwach (report).....Aug. 2—117-132
Monarch turns out its 50,000th lathe .....Nov. 22—164
Old gear makes dividing-head lathe. J. M. Heath (P.I.).....Aug. 16—147
Phoenix Products Co.'s metal spinning lathe world's largest.....June 21—174
Planetary fixture mills flats in position in turret lathe. Robert Wiedenholt (P.I.) .....Mar. 15—166
Setup bores large work on lathe with short bed. M. L. Gupta (P.I.) Dec. 6—176
Shell lathes aided by cam feed. S. F. Pasternak .....Apr. 26—110
Side-drilling in turret lathe drills work in place. M. Yamaguchi (P.I.) Feb. 1—125
Simple rotary shear on lathe. H. J. Gerber (P.I.) .....July 5—152
Solenoid stops VTL ram feed. J. K. Gensler (P.I.) .....July 19—147
Turnabout banjo tooling (cover) May 10— 2
Turnabout tooling cuts time on banjo .....May 10—130
Turret lathe bores from solid—with turret tool—with toolpost tool....Aug. 2—155

Layout:

Cope talks on draw dies. S. R. Cope Pt. 8 Wide-flanged shells draw easily if you follow the rules.....Jan. 4—100

(ed) Editorial (P.I.) Practical Ideas

Pt. 9 Know the wrinkles about spherical shells ..... Feb. 15—148
Pt. 10 Reverse drawing gives you greater reductions ..... Mar. 15—134
Pt. 11 Observe 6 rules when making tapered shells ..... Apr. 26—114
Pt. 12 Tapered shells require skillful operation layout ..... May 10—168
Pt. 13 Iron shells to get accurate diameters for smooth finish ..... June 7—134
Pt. 14 Three shell jobs typify ironing operations ..... July 5—126
Pt. 15 Necked shells require careful reductioe ..... July 19—130
Pt. 16 Make offsets in dies or on lathes ..... Aug. 2—134
Pt. 17 Choose from 4 methods to bulge shells ..... Aug. 16—122
Pt. 18 Fluid dies bulge shells and form ornamental design ..... Aug. 30—109
Drilled plate aids layout of equidistant holes. J. M. Heath (P.I.) May 24—151
Duplicator eases progressive die layout. H. J. Gerber (P.I.) ..... Nov. 22—151
Knife-edged sine square for easy layout. Jack Dalton (P.I.) ..... Nov. 22—150
Layout dye speeds machining. Carl Jensen (P.I.) ..... Nov. 22—149
Right-angle V-block for circular layout. W. Trimailo (P.I.) ..... Feb. 15—167
Seismograph places grinders (chart) .. Apr. 12—209
Surface swabbed with layout dye aids measurement. Gus Wernberg (P.I.) July 19—146
Leipzig Fair — Iron Curtain is lifted to show machine tool progress ..... Oct. 11—192
Standardization characterizes communist-built machine tools. David Scott ..... Feb. 15—158
Lights and Lighting—Practical "lab" tests light and quiet at Wakefield Brass Co. C. A. Schroders ..... May 24—124
Lot Sizes—Minimum economical lot sizes. Tyler Hicks (chart) (Ref. Bk. Sheet) Feb. 15—171
Lubrication—How to bend aluminum tube and bar. J. M. Adle (report) ..... May 24—137-144
New look at cutting fluids. H. N. Leave Mar. 1— 97

M

Machine Tool Electrification Forum Apr. 26—153

Machinery:

American Institute of Electrical Engineers' Conference on Machine Tools deals with automation ..... Nov. 8—175
American Machine Tool Distributors' Assn. sees replacement as the biggest potential market for machine tools Nov. 8—176
American Machinist production nuggets of assembling, welding, portable tools (chart) ..... Mid-Nov.—F1-15
American Machinist production nuggets of tooling ..... Mid-Nov.—C1-13
British machine tools: business is good Aug. 2—156
Canada—metalworking's land of promise (report) ..... May 24—129-136
Canadian Trade Fair: eight nations compete for machine-tool business June 21—166
Check list for machine care. Frank Biechele (Ref. Bk. Sheet) ..... Feb. 1—135
CIT offers tool financing plan Oct. 25—178
Dealers ask lower freight rates for shipment of used machinery Mar. 15—185
Ford Motor mothballing machine tools May 24—166
German machine tools dominate Vienna Fair ..... May 24—164
Get your special machines off to a good start—design and construction at Delco-Remy. C. A. Nichols ..... Feb. 15—121
Getting the most out of your machines (ed) ..... Nov. 8—115
Grinding machine firm will lease and rebuild, allow trade-ins and time payments ..... Dec. 20—137
Home-made machines make tabulator parts at Remington-Rand ..... Aug. 16—144
Index of new orders for machinery announced by McGraw-Hill (charts & tables) ..... Mar. 15—178
Japan: industry on the rebound June 21—172
Leipzig Fair 1954: Iron Curtain is lifted to show machine-tool progress Oct. 11—192
Leipzig Fair—standardization characterizes communist-built machine tools. David Scott ..... Feb. 15—158
Less-developed countries potential market for US exports ..... Oct. 11—189
Milan Fair 1954 ..... Oct. 11—186
"Most flexible finance-leasing plan" offered by Jones & Lamson and CIT Aug. 2—158
NMTBA 52nd meeting discusses machine-tool redesign ..... May 24—162
New plan for government machine tools ..... Dec. 20—134
1954 production preview of new metalworking equipment, parts and materials ..... Jan. 18—121-264
No raids on machine tool reserves (ed) Aug. 30— 83
Realistic depreciation rates. Burnham Finney (chart) (report) .. Mar. 1—113-120
Replacement discussed by New England conference ..... May 10—194
Replacement—market with a future (ed) June 21—115
Replacement of capital equipment discussed at AMA meeting ..... May 24—169
Sharp upturn in machinery new orders (except electricrl) registered by McGraw-Hill index (chart) ..... Aug. 2—158
Synchromacion speeds output of standard machines. B. C. Brosheer. Dec. 20—110
Today's machine tools: what does industry expect of them ..... Nov. 8—180
Trade with Russia—once banned metalworking equipment can be exported Sept. 13—198
US machine tool inspection completed Aug. 2—157
Used machine tools are big ($300 million a year) business (chart) .. Feb. 1—142
Used machinery: second line of industrial defense? ..... May 24—170
Used machinery: will taxes rock the boat? ..... May 10—196
Vance Plan: is the Pentagon putting roadblocks in its way? ..... Mar. 29—140
Machinery & Allied Products Institute—Annual meeting ..... July 5—169
Machinery Dealers National Assn. asks lower freight rates for shipment of used machinery ..... Mar. 15—185
Magnesium—Dow plunges on integrated mill for magnesium ..... June 7—176
Magnesium Assn.—Meeting spotlight was hot-chamber die casting ..... Dec. 6—194

Magnetic Equipment:

Electromagnetic platen for cradle grinding makes abrasive belts more automatic ..... Feb. 15—153
Know your magnetic chucks. H. Gifford July 5—122
Notched parallels for magnetic tables. Robert Wiedenhoft (P.I.) ..... Aug. 16—145
Paper makes magnet easier to use. L. H. Austin (P.I.) ..... Aug. 2—138

Maintenance:

"Dieset comparator" easily made from stock parts. Jerry Coates (P.I.) .. Oct. 11—175
Drill length and causes of drill breakage (Ref. Bk. Sheets) (chart) .. Oct. 11—183
Foam-cooling method increases tool life and improves work conditions. Mason & Weber (chart) ..... Apr. 12—174
How to babbitt a large bearing. H. E. Linsley ..... Aug. 30— 98
How to control corrosion. C. D. Emerson (report) ..... Dec. 6—145-160
Magnetic parallels for safer repairs. Henry George (P.I.) ..... Oct. 11—174
Oil for power steering tests purified and re-used. J. A. Hudson ..... Aug. 30— 92
Old masters' touch salvages scrap parts ..... July 5—117
Repair for threading dies. F. Strasser (P.I.) ..... Dec. 20—120
Ryan Aeronautical saves $20,000 a month with air-tools ..... Mar. 15—153
Simple repair for broach puller. S. George (P.I.) ..... Oct. 11—174

Management:

American Machinist production nuggets of management, personnel (charts & tables) ..... Mid-Nov.—A2-19
Are you a visual or a verbal man? J. J. Jehring ..... Dec. 6—129
Co-determination (ed) ..... Dec. 20— 87
Get returns from foreman training. G. S. Odiorne ..... Dec. 6—137
How to coordinate subcontracting to meet production schedules. G. E. Fouch (report) (charts) ..... Feb. 15—137-144
Invitation to disaster (ed) .. Oct. 11—127
It's the people who count (ed) .. Mar. 15—119
Minimum economical lot sizes. Tyler Hicks (Ref. Bk. Sheets) (chart) .. Feb. 15—171
Modern metalworking in Mexico. F. H. Colvin ..... Aug. 2—104
Mutual hiring saves headaches for small plants ..... Feb. 1—121
Personal interest and guards . . . cut accidents, boost production. C. L. Morgan ..... Sept. 13—178
Product-market diversification. A. H. Jones ..... Aug. 16—130
Separating the men from the boys (ed) Nov. 22—111
Shop thief. B. A. Hall ..... Mar. 15—156
Simple system streamlines job-shop operation. G. H. DeGroat .... Sept. 13—176
Suggestion plans—what makes them work? V. H. Rotroff ..... July 19—144

Mandrels:

Eccentric-mounted mandrel relieves form cutters. G. W. Wilson (P.I.) Aug. 2—139
Matching angle irons. W. J. Morgan (P.I.) ..... Aug. 16—147
Russians harness plastic mass for actuating medium ..... June 21—126
Markers and Marking—Adjustable scriber simplifies vernier height gage settings. R. H. Fry (P.I.) ..... Aug. 16—147
Materials—American Machinist production nuggets of materials and components (table) ..... Mid-Nov.—H1-13
Hot machining cell at Oak Ridge (cover) Apr. 12— 2

Materials Handling:

American Machinist production nuggets of materials handling and plant service ..... Mid-Nov. I1-17
Assembly of complicated machines simplified at Burroughs Corp. ..... May 10—161
Automation . . . combines standard lathes. E. J. Tangerman ..... Mar. 29—110
Automation advantageous for small shops. J. B. Cunningham (report) (charts) ..... Apr. 12—177-184
Big plant tooling in a small shop. G. H. DeGroat ..... June 7—138
Canny bulk handling saves chip and oil wastes. Lindsay & Graves .. Mar. 15—130
Dieset "take-apart" cart saves time, cuts die damage. J. G. Schlindwein. Mar. 1—110
Drill units move tools to work. C. A. Wiken ..... May 24—122
Drum-lifting tongs handle pots of radioactive parts. A. A. Denst (P.I.) .. Oct. 25—163
Lathe-chuck crane aids handling, storage. Terry & Stuart (P.I.) .. Nov. 22—148
Marking of compressed gas containers. R. R. Fetherstone (Ref. Bk. Sheets) .. Sept. 13—191
New wrinkles for an old plant. R. Sheets June 7—129
Plastic barge for shallow waterways Oct. 25—178
Slide attached to shear catches workpieces. M. Yamaguchi (P.I.) .. Mar. 15—166
Westinghouse integrates fast production with 51 conveyor systems to produce two refrigerators a minute. G. H. DeGroat ..... May 10—157
McGraw, F. H. & Co.—New techniques build new atom plant, Paducah, Ky. Jan. 4— 92
McGraw Hill Index of New Orders for Machinery announced (charts & tables) Mar. 15—178

Measuring:

Adjustable scriber simplifies vernier height gage settings. R. H. Fry (P.I.) ..... Aug. 16—147
Comparator measures to 0.0001 in. G. Lee (P.I.) ..... Dec. 20—118
Die-opening dimensions measured by thin lead plate. Erik Roed (P.I.) .. May 24—150
Drilled plate aids layout of equidistant holes. J. M. Heath (P.I.) .. May 24—151
Layout dye aids measurement. Gus Wernberg (P.I.) ..... July 19—146
Long gaging job (cover) ..... May 24— 2
Measuring the first "jo" block. Apr. 12—255
Optical method of measuring alignment errors in micrometers. John P. Wright (chart) ..... Apr. 12—168
Plug constants for checking dovetails. Donald Sweet (Ref. Bk. Sheets) (tables) ..... Aug. 30—123
Simple scale measures compression and tension. Chris Stougaard (P.I.) .. Apr. 26—137
Spun steel heads for biggest clamshell July 5—167
Thermal number measures efficiency of metal cutting. K. J. Trigger (report) (charts) ..... June 7—145-152
Titanium is unorthodox when machined . . . here's why. M. E. Merchant & others (charts) ..... July 5—118
Metal Powder Assn.—10th annual meeting May 24—167
Metal Treating Institute meeting .. Nov. 22—164

Metals:

American Machinist production nuggets of materials and components ..... Mid-Nov.—H1-13
Annealing and hot working of metals. Samuel Storchheim (charts & tables) (report) ..... Sept. 13—161-168
How to understand cold working of metals. Samuel Storchheim (charts & tables) (report) ..... Aug. 30—101-108
How to understand heat-treatment processes. Samuel Storchheim (charts) Apr. 26—126
Pure metals direct from raw ores. June 7—174
Tantalum and columbium properties and methods of working. J. W. Rose (report) (charts & tables) .. Apr. 12—189-198

(ed) Editorial (P.I.) Practical Ideas

Metalworking:
American Machinist Index of Metalworking Production (charts & tables) Mar. 29— 97
Anti-merger law: Clayton Act has teeth, steel firms find ..... Oct. 25—174
Better adapt yourself—or give up (ed) Aug. 16—115
Boys from Syracuse point the way (ed) Feb. 1— 95
Canada—metalworking's land of promise (report) ..... May 24—129-136
Modern metalworking in Mexico. F. H. Colvin ..... Aug. 2—104
New equipment at tool show ... Apr. 12—217
New U.S. tax laws—how they affect metalworking (charts) ..... Sept. 13—194
1955 Production Planbook for Metalworking (charts & tables) ..... Mid-Nov.
1954 outlook (charts) ..... Apr. 26—150
1954 Tool Show ..... Apr. 12—250
1954 production preview of new metalworking equipment, parts and materials Jan. 18—121-264
1970 style of metalworking (ed) .. Aug. 2— 99
Numerical control, what it means to metalworking. Stocker Jr. & Emerson (table) (report) ..... Oct. 25—133-156
Realistic depreciation rates. Burnham Finney (report) (chart) .. Mar. 1—113-120
Sweden eyes Russian metalworking market ..... Sept. 27—161
Textile firm, Susquehanna Mills, goes into metalworking ..... Mar. 29—145
U.S. industry will have to expand 65% to meet 1970's market (charts) Aug. 2—150
Mexico—Modern metalworking in Mexico. F. H. Colvin ..... Aug. 2—104
Mica—Artists sculpture mica dies. J. P. Wright (charts & tables) (report) .... Sept. 13—145-160

Micrometers:
Checking depths aided by spring wire. Robert Roedder (P.I.) ..... Apr. 12—213
Frames support inside micrometers. A. Y. Patel (P.I.) ..... Dec. 20—119
Optical method of measuring alignment errors. John P. Wright (chart) ... Apr. 12—168
Stepped plate aids reconditioning. M. Barash (P.I.) ..... Mar. 15—168
Milan Fair—Fourth Annual European Machine Tool Exhibition ..... Oct. 11—186

Milling and Milling Machines:
American Machinist production nuggets of machining (charts & tables) .... Mid-Nov.—B1-3)
Chemical milling: now the "impossible" doesn't take longer ..... Sept. 13—200
Fixture for milling flats on drills. Edward Schmidt (P.I.) .... Aug. 30—114
Fixture loads itself from conveyor (cover) ..... Oct. 11— 2
Hinged spacers aid milling flats. L. H. 1 & 2 ..... Aug. 2—117-132
Hoist and rack handle milling heads. Oscar Wittlinger (P.I.) ..... Oct. 11—173
Indexing head to mill square ends. Irving Epstein (P.I.) ..... Jan. 4—118
Ingenious holding method helps mill helical groove. A. Vetsch (P.I.) .. June 7—157
"Jet Bore" probably most powerful machine tool (cover) ..... Apr. 26— 2
Mighty mill (cover) ..... Sept. 13— 2
Mill on wheels (cover) ..... July 19— 2
Mist cooling goes to work (report) Pts. 1 & 2 ..... Aug. 2—117
One-piece hammer and crank tightens milling vises. Henry Gifford (P.I.) . Jan. 4—118
Pick-a-back tooling machines forgings for giant press. W. M. Stocker, Jr. July 19—117
Planetary fixture mills flats in position in turret lathe. Robert Wiedenholt (P.I.) ..... Mar. 15—166
Rotating flycutter mills spheres with single-point tool. Louis Saiia (P.I.) Apr. 26—136
Russia's giant plano-miller .... Oct. 11—195
Shop hints help form and mill titanium Sept. 13—129
Soft iron cylinder holds end mill. L. R. Choudhary (P.I.) ..... Feb. 1—128
Spherical bore milled with single-point tool. J. E. Harwood (P.I.) ... Mar. 29—129
Simple contour-milling attachment. C. B. Weidner (P.I.) ..... July 5—149
Spar-skin mill machines entire plane sections in a single operation ..... June 7—170
"Tandem" drive mills keyway in large shaft. John Emrich (P.I.) ... Aug. 30—113
Threaded arbor saves straddle-mill setup time. Henry George (P.I.) ... Apr. 26—138
Tilted templet reproduces correct form for milling. H. K. Fronicke (P.I.) Jan. 4—119
Ti-stainless machined like butter. George Glaeser ..... Sept. 13—144
Vacuum chuck and special table increase milling range. R. W. Holmes (charts) Apr. 12—210
World's largest boring mill? Germany's Schiess AG built it, but Russia has it Mar. 1—138

Modernization:
Big plant tooling in a small shop. G. H. DeGroat ..... June 7—138
Hot machining cell at Oak Ridge (cover) Apr. 12— 2
Ingersoll Milling Machine Co.: The Trend ..... Apr. 26—154
Machine Tool Electrification Forum theme ..... Apr. 26—153
"New look" hits Caterpillar plant June 7—178
Plant modernization stressed at NMTBA meeting ..... Dec. 6—186
Spring-clean your business (ed) .. Apr. 12—159
Realistic depreciation rates. Burnham Finney (report) (chart) .. Mar. 1—113-120
Packard slates $50 million tooling for initial modernization move ... Mar. 15—183
What regularized replacement can do (ed) ..... Apr. 26— 99

Molds and Molding:
American Machinist production nuggets of pressworking, molding, casting .... Mid-Nov.—D1-17
Hard bronze inserts for drawing and forming stainless dies without scratches. Arnold Walz ..... Aug. 2—106
Is shell molding practical for job lots? F. K. Shallenberger (table) Oct. 25—130

Motors—Output shaft of differential controls speed from 0 to 300 RPM. Chris Stougaard (P.I.) ..... Mar. 1—127

Munitions:
Cam feed speeds undercutting on 75-mm shell. S. F. Pasternak ..... Apr. 26—110
Cold extruding rocket noses .... May 24—169
Conventional tools machine titanium for aircraft gun parts. Roland Satterlee Aug. 30— 94
Guided missiles: is technical cloak-and-daggerism hiding a snafu? .... July 5—162
How U.S. Navy probes bores. J. A. Penn Mar. 15—160
Offshore ammunition procurement for Nato: Senate raps European buildup —U.S. cutback ..... Aug. 30—132
Screw-machine converted for gun-drilling. W. M. Stocker, Jr. ..... Feb. 15—162
U.S. guided missile program .... Mar. 1—138

N

National Aeronautic Production Forum .... Apr. 26—152
National Labor Relations Board—Taft-Hartley's new look—reinterpretation of its regulations ..... Aug. 30—126
National Machine Tool Builders Assn.—52nd meeting discusses machine-tool redesign May 24—162
1955's Machine Tool Show: Chicago will be the showcase for 150 U.S. builders ..... Nov. 22—162
Production engineering show to complement 1955's Machine Tool Show .... Dec. 6—193
Stress on plant modernization Dec. 6—186
National Metal Exposition & Congress—Metal Show, four society technical program draws record 63,500 ..... Nov. 22—166
National Screw Machine Products Assn.—Optimistic outlook keynotes meeting . May 10—195
National Tool & Die Manufacturers Assn.—Annual meeting hears Commerce Dept. official—"Tool and die business, good but competitive" ..... Nov. 22—168
Noise—Practical "lab" tests light and quiet at Wakefield Brass Co. C. A. Schroeder May 24—124
Nomograph—Aids solution of worm-thread profiles. O. Saari (charts & tables) ... July 5—113
Notching—Versatile producer . . . the press brake. J. W. Matthewman. Pt. 2 Piercing and notching units permit progressive setups ..... Jan. 4— 96
Nuts—Ring nut fastening method. G. R. Milner (P.I.) ..... Oct. 11—173
Simple locknut method. Federico Strasser (P.I.) ..... Apr. 26—136

O

Obsolescence:
Invitation to disaster (ed) ..... Oct. 11—127
Prescription for prosperity: timely replacement of capital equipment . Feb. 1—140
Realistic depreciation rates. Burnham Finney (report) (chart) .. Mar. 1—113-120
Office of Defense Mobilization—No raids on machine tool reserves (ed) .... Aug. 30— 83
Vance heads new ODM Industry Review Board ..... Aug. 30—127
Oil Reclamation—Canny bulk handling saves chip and oil wastes. Lindsay & Graves Mar. 15—130
Purified and re-used oil for steering tests. J. A. Hudson ..... Aug. 30— 92
Optical Instruments—Plate-glass extension adds capacity to comparator. Ottavio Cerullo (P.I.) ..... May 10—174

P

Paints and Painting—Flow coating plane parts increases paint shop output 116% at Northrop ..... Sept. 27—154
Longest continuous flow coating line paints 6400 parts per hour at Douglas ..... Oct. 11—190

Parallels:
Circular parallels of steel pipe and tubing to avoid accidents. Henry George (P.I.) ..... Aug. 2—137
Erasers support thin parallels. Federico Strasser (P.I.) ..... June 21-145
Magnetic parallels for safer repairs. Henry George (P.I.) ..... Oct. 11—174
Notched parallels for magnetic tables. Robert Wiedenhoft (P.I.) ... Aug. 16—145
Photographic records—For tooling setups saves time and money. H. J. Friedman Dec. 6—134
Piercing—Half-piercing locates parts for rivets or welding. M. Yamaguchi (P.I.) Mar. 15—166
Versatile producer . . . the press brake. J. W. Matthewman. Pt. 2 Piercing and notching units permit progressive setups ..... Jan. 4— 96

Pins:
Devices eliminate shear pins. W. C. Betz (P.I.) ..... June 21—148
Diamond pin design. W. Paul Wing (Ref. Bk. Sheet) (chart & table) .. Mar. 29—137
In-place-machined pivot pin saves downtime of crane. Peter Cervelli (P.I.) Apr. 26—138
Pressure-pin aids part ejection. G. J. Bowman (P.I.) ..... Jan. 4—117
Split cotter pins do variety of jobs. T. H. Duffy (P.I.) ..... June 7—157
Pipes—Ten steps make sports-car tailpipes. Carl Koonter ..... Oct. 25—158
Turning and threading pipe ends for high-pressure couplings ..... Nov. 22—166

Planers:
Brass lifter aids undercutting in planer. R. K. Edwards (P.I.) ..... Mar. 15—168
Hinged toolholder planes parallel grooves. H. M. Mason (P.I.) .... Sept. 13—181
Mist cooling helps some planer jobs. Feuerpfeil, Titus & Thuerwachter (report) Pt. 2 ..... Aug. 2—129
Traverse one planer tool to cut radius with other tool. R. K. Edwards (P.I.) Feb. 15—168

Plant Layout:
Layout of the bearing line and the automatic handling equipment in a Moscow plant. David Scott ..... Oct. 11—164
Modern metalworking at Ciudad Industrial DM Nacional plant in Mexico. F. H. Colvin ..... Aug. 2—104
New wrinkles for an old plant. R. Sheets June 7—129

Plants:
Automation advantageous for small shops. J. B. Cunningham (charts) (report) ..... Apr. 12—177-184
Hot machining cell at Oak Ridge (cover) Apr. 12— 2
Washington's industrial flux .. Nov. 22—169
Why . . . production-wise, plant-protection foolish? W. K. Ousley .. May 24—146

Plastics:
Convair—methods of tooling with plastics. H. H. Rosenbaum .... Mar. 15—121
Holes pulverized in plastics. A. L. Levitt ..... Oct. 11—144
How to centerless-grind parts of plastic and wood rod. Gentile & Schaper .... May 10—134
How to machine acrylic plastics. Dr. O. L. Pierson (report) (tables) ..... Feb. 1—113-120
Little dies lick big costs in short-run plastics. Edward Douglas .... Sept. 27—124
Roll flowing saves operations and conserves materials in plastic deformation. C. L. Sporck ..... Mar. 29—104
Russians harness plastic mass for actuating medium ..... June 21—126

Plates:
Biggest plate stretcher (cover) . Mar. 15— 2
Die-opening dimensions measured by thin lead plate. Erick Roed (P.I.) . May 24—150

(ed) Editorial (P.I.) Practical Ideas

Slot for indexing plate locating. H. J. Gerber ..... Nov. 22—148
Stretch aluminum plate to reduce machining distortion. Lawler & Binkley (tables) ..... Mar. 15—128

Plating:

Chemical-nickel process plates metal any size and shape ..... Dec. 20—134
Hard chrome can be plated to "tenths" in production. George DeMirjian (chart) ..... Aug. 2—101
Hard chrome plate pays unexpected dividends. White & McKean ..... Aug. 16—142
How to nickel-plate aluminum for solder joining. W. M. Stocker, Jr. ..... June 7—154
"Pushbutton" plating at Pontiac saves nickel ..... Dec. 20—136

Polishing:

Automatic polishing machine. F. E. Riley (P.I.) ..... June 21—145
Contact wheels influence abrasive-belt performance. Direk Olton ..... June 21—121
Fixture helps polish small-diameter pivots. Giroa Herzl (P.I.) ..... May 24—151
How to choose power brushes. R. O. Peterson (charts) (Ref. Bk. Sheets) Pts. 1, 2 & 3 ..... Oct. 25—167

Powder Metals:

Machining porous powder-metal parts. Langhammer & Glick (charts) ..... Apr. 26—101
Metal Powder Assn. 10th annual meeting ..... May 24—167
Sheet metals can be made from metal powder. W. D. Jones ..... June 7—142
Practical Ideas—1954 prize-winning Practical Ideas ..... Mid-Nov.—J1-7
Pressed Metals Institute—Discusses metal stampings outlook ..... Dec. 6—193
Meeting ..... Mar. 29—147
Meeting discusses new markets ..... Sept. 13—202

Presses:

Air Force Heavy Press Program gets underway at Alcoa, Lafayette ..... June 7—173
Air press helps thread sheet metal lever. John Muth (P.I.) ..... Apr. 12—216
Alcoa's bandsaw (cover) ..... Dec. 6— 2
American Machinist production nuggets of pressworking, molding, casting (tables) ..... Mid-Nov.—D1-17
Big stretch press goes in (cover) ..... Aug. 16— 2
Drillpress fixture speeds second operation. Edward Schmidt (P.I.) ..... Apr. 12—214
Forging presses replaces hammers and high-frequency heating has taken place of oil and gas in Russia ..... Aug. 30—130
High-pressure forming press for jet planemaking operations ..... Sept. 27—158
Hot extruding aluminum fan blades to 0.001-in. tolerance in 1100-ton press ..... Feb. 15—184
How to choose hydraulic presses for metal forming operations. H. D. Thweatt (report) ..... Mar. 29—115-126
Northrup to install US' largest sheet metal stretch press ..... July 5—169
Pick-a-back tooling machines forgings for giant press. W. M. Stocker, Jr. ..... July 19—117
Punch presses with mufflers make less noise, eject parts more effectively. J. G. Schlindwein ..... Sept. 13—180
Rebuilt 50-ton press burnishes axle housings. E. D. White (P.I.) ..... Mar. 1—125
Replacement study pays off for spring maker. J. R. Nikolais ..... Dec. 20—130
"Safety sheet" avoids overload on blanking and forming press. F. Strasser (P.I.) ..... Dec. 20—120
Small hydraulic presses do yeoman work. R. H. Behrend ..... Oct. 25—126
Special tools support 14,000-ton extrusion press. W. C. Winter (table) ..... Dec. 6—162
Tension for press setup checked with gage bar. A. Vetsch (P.I.) ..... Feb. 1—127
Test forging 5000-lb ingots for AF heavy presses ..... July 19—164
2-ton carbide pieces in a 220-ton press ..... Mar. 15—185
Versatile producer . . . the press brake (tables) J. M. Matthewman
Pt. 2 Piercing and notching units permit progressive setups ..... Jan. 4— 96
Pt. 3 Think of press brakes beyond the first job ..... Feb. 1—108
Pt. 4 For safety, bend according to the rules ..... Nov. 22—116
You can miter strip stock, too. L. W. Tiefel ..... Oct. 11—139
Pressure transmission — Russians harness plastic mass for actuating medium ..... June 21—126

Prices:

American Machinist index of metalworking prices ..... Mid-Nov.— 25
FTC hits volume discounts violating the Robinson-Patman Act ..... Aug. 16—164
Metalworking—1970 style (ed) ..... Aug. 2— 99
Metalworking's long view: needed—65% expansion of US industry to meet 1970's market (charts) ..... Aug. 2—150

Production:

American Machine Tool Distributors' Assn. sees replacement as the biggest potential market for machine tools ..... Nov. 8—176
Canada—metalworking's land of promise (report) ..... May 24—129-136
Getting the most out of your machines (ed) ..... Nov. 8—115
Metalworking's long view: needed 65% expansion of US industry to meet 1970's market (charts) ..... Aug. 2—150
New ODM Industry Review Board program for production capacity ..... Aug. 30—127
1955 Production Planbook for Metalworking (charts & tables) ..... Mid-Nov.
Quick federal spending: is it the push that will start the business swing upward? ..... Aug. 16—161

Production Methods:

Air power used for machines at Kwikset Locks, Inc. ..... Apr. 26—106
Assembly of complicated machines simplified at Burroughs Corp ..... May 10—161
Automatic brushing deburrs turbine disks. DePastina & Eyre ..... July 5—124
Automation-intermachine materials handling—combines standard lathes. E. J. Tangerman ..... Mar. 29—110
Automatic machine control for job-lot production seen as outgrowth of GE electronic system ..... Feb. 15—182
Better adapt yourself—or give up (ed) ..... Aug. 16—115
Building supersonic planes creates new production problems. A. Ashburn (report) ..... July 5—129-144
Carbide tooling succeeds on automatics ..... July 19—158
Chemical milling of aircraft sections is fast and cheap ..... Sept. 13—200
Cold-forming gears and splines ..... June 21—169
Continental Motors production shortcuts help power tanks. G. H. DeGroat ..... July 19—122
Conventional tools machine titanium. Roland Satterlee ..... Aug. 30— 94
Curved slots are drilled and cut in a timesaving method. H. P. Kunkleman ..... Aug. 2—110
Cylinder assemblies speed up diesel production ..... Mar. 29—108
Diversification of product-market. A. H. Jones ..... Aug. 16—130
Dodge gages V-8 bores in the machine shop. B. S. MacPhail ..... Oct. 11—134
Eight ways to make pneumatics practical. L. H. Kirk ..... June 21—130
Electrical discharge machining on production basis applied at Watertown Arsenal. Anderson Washburn (charts) ..... Apr. 12—185
Fixture loads itself from conveyor (cover) ..... Oct. 11— 2
Ford output upped with Canadian transfer unit ..... June 21—166
Good tooling plus dial feeds will cut stamping costs. W. W. Schug ..... Oct. 11—129
Hard bronze inserts for drawing and forming stainless dies without scratches. Arnold Walz ..... Aug. 2—106
Hard chrome can be plated to "tenths" in production. George DeMirjian (chart) ..... Aug. 2—101
High-speed trepanning at Bethlehem Steel. W. M. Stocker, Jr. (report) ..... Jan. 4—105-114
Hot-spinning stainless (cover) ..... Sept. 27— 2
How long can the cycle last? (ed) ..... Oct. 25—115
How Ryan forms and welds titanium ..... Dec. 6—138
How to babbitt a large bearing. H. E. Linsley ..... Aug. 30— 98
How to coordinate subcontracting to meet production schedules. G. E. Fouch (report) (charts) ..... Feb. 15—137-144
How to form integrally stiffened skins W. T. Kluge (report) ..... Nov. 22—129-140
How to stretch-form aluminum. J. M. Adle ..... July 19—133
How to understand cold working of metals. Samuel Storchheim (charts & tables) (report) ..... Aug. 30—101-108
How to work stainless steel. R. E. Paret (tables) (report) ..... Sept. 27—129-140
Improved bolt design. M. Brenner ..... July 5—146
Japan: industry on the rebound ..... June 21—172
Jones & Lamson cut production time 27% with wage incentives. R. S. Jones ..... May 24—118
Metalworking—1970 style (ed) ..... Aug. 2— 99
New wrinkles for an old plant. R. Sheets ..... June 7—129
1954 production preview of new metalworking equipment, parts, and materials ..... Jan. 18—121-264
Note from Moscow (ed) ..... May 10—119
Perpetual motion saves money in contouring generator shaft ..... Oct. 25—122
Personal interest and guards . . . cut accidents, boost production. C. L. Morgan ..... Sept. 13—178
Photographing tooling setups makes "trick methods" available for less experienced workers. H. J. Friedman ..... Dec. 6—134
Pre-positioned setups speed job-lot production ..... Dec. 6—142
Process evaluation pays long-term dividends. W. M. Stocker Jr. (report) ..... June 21—133-140
Punch presses with mufflers eject parts more effectively. J. G. Schlindwein ..... Sept. 13—180
Quality control should be supervised by production. D. R. King ..... July 19—128
Railroad axles roller-bearinged at freight-car production speeds at American Car & Foundry. E. J. Tangerman ..... Jan. 4—130
Separating the men from the boys (ed) ..... Nov. 22—111
Sheet metals can be made from metal powder. W. D. Jones ..... June 7—142
Shop hints help form and mill titanium ..... Sept. 13—219
Side cams on assembly die speed switch assembly. Federico Strasser (P.I.) ..... Aug. 16—145
Silver brazing goes semi-automatic. Spiesz & Leuthner ..... May 10—121
Simple system streamlines job-shop operation. G. H. DeGroat ..... Sept. 13—176
Soviet challenge in productivity (ed) ..... Mar. 1— 95
Spring-clean your business (ed) ..... Apr. 12—159
Ten steps make sports-car tailpipes. Carl Koonter ..... Oct. 25—158
3 colors from 1 inventory with precoated metal coil, flashlight batteries ..... Jan. 4—104
Tools for precision from Ford Instrument. W. M. Stocker, Jr. ..... June 21—117
Trepanning titanium cylinders from solid billets. Siemen & Rosato ..... Aug. 30— 89
Tubing patterns from a single sheet of metal ..... Nov. 8—178
Turnabout tooling cuts time on banio ..... May 10—130
UHF contacts for electronic oscillators formed four times faster. C. S. Selby ..... Feb. 1— 97
Versatile producer . . . the press brake (tables) J. M. Matthewman
Pt. 2 Piercing and notching units permit progressive setups ..... Jan. 4— 96
Pt. 3 Think of press brakes beyond the first job ..... Feb. 1—108
Pt. 4 For safety, bend according to the rules ..... Nov. 22—116
Wage incentive plans—put Standard Minute plan to work. K. L. Kline (chart & table) ..... Mar. 1—106
Westinghouse integrates fast production with 51 conveyor systems to produce two refrigerators a minute. G. H. DeGroat ..... May 10—157
Pumps—Projected profit and loss statement for three plans of producing oil pump bodies (table) ..... Feb. 1—141
Testing pumps and valves for power steering units. J. A. Hudson ..... Aug. 30— 92

Punches:

Attachment to shaper cuts hand work on punches. H. Gifford (P.I.) ..... Feb. 15—166
Clearance between a punch and die. D. R. King (Ref. Bk. Sheets) Pts. 1 & 2 ..... Apr. 12—245
Guided punch speeds layout. H. J. Gerber (P.I.) ..... Oct. 11—172
Hardened guides eject slug problem. J. G. Schlindwein (P.I.) ..... Mar. 15—163
Muffler ejector nozzle to suit individual press job to eject punched part better. J. G. Schlindwein ..... Sept. 13—180

Quality Control:

American Machinist production nuggets of inspecting, testing, quality control ..... Mid-Nov.—E1-5
Contacts in fixtures assure repetitive accuracy. F. E. Piekos ..... Oct. 11—136
Dial feeds on presses save labor and improve quality. W. W. Schug ..... Oct. 11—129
"Excess rejects" spot process troubles. Sterling Winchell ..... Oct. 11—142
Exposing machine-tool gremlins with high-speed photography. L. C. Tullis (chart) ..... June 7—156
Gas-welding hard surfaces for precision. John Wischhusen ..... May 24—126
Process evaluation pays long-term dividends. W. M. Stocker, Jr. (report) ..... June 21—133-140
Production should supervise quality control. D. R. King ..... July 19—128
Production tools for precision from Ford Instrument. W. M. Stocker, Jr. ..... June 21—117

(ed) Editorial (P.I.) Practical Ideas

"Pushbutton" plating at Pontiac saves nickel, improves quality....Dec. 20—136

R

Racks—Hoist and rack handle milling heads. Oscar Wittlinger (P.I.).....Oct. 11—173

Radii:

Radius slot on hardened 8713 steel "ground" by carbide bur. E. J. Tangerman (charts) .....Apr. 12—172
Simple gage measures large radius. A. C. Chattacharyya (P.I.) ...Dec. 6—174
Standard milling cutter forms large radius. Henry George (P.I.) Feb. 1—126
Traverse one planer tool to cut radius with other tool. R. K. Edwards (P.I.) Feb. 15—168

Radioactivity—To machine radioactive materials . . . atomic-submarine power plant. S. L. Lindbeck .....Apr. 12—166
Radiography—Industrial betatron for radiographic examinations at Detroit Arsenal Aug. 16—160

Reamers and Reaming:

American Machinist production nuggets of machinery (charts & tables) Mid-Nov. B1-37
Floating reamer-holder for knee tools. D. Moore (P.I.) .....Aug. 30—116
Threaded stud aids tapered reamer. Max Karfunkel (P.I.).....Dec. 6—175

Reference Book Sheets
Jan. 4—123, Jan. 18—267, Feb. 1—131, Feb. 15—171, Mar. 1—131, Mar. 15—171, Mar. 29—133, Apr. 12—243, Apr. 26—143, May 10—179, May 24—155, June 7—163, June 21—159, July 5—155, July 19—151, Aug. 2—143, Aug. 16—151, Aug. 30—119, Sept. 13—187, Sept. 27—147, Oct. 11—179, Oct. 25—167, Nov. 8—167, Dec. 6—179, Dec. 20—123

Republic Aviation Corp.—Training supervisors for tomorrow. Wm. M. Stocker, Jr. .....Aug. 16—133

Research:

Bubbles double as grains: have similar growing pains .....July 5—168
Manufacturing Research Dept. to find out what users want in machine tools Nov. 8—180
New Ford research center.....July 5—168
Press-replacement study pays off for spring maker. J. R. Nikolais ..Dec. 20—130
Pure metals direct from raw ores . June 7—174
Spot welding of titanium is a practicable method of assembly research program shows. Begeman & McBee (charts & tables) .....Dec. 20— 98
Study of heat vs. cold showed no relationship between temperature and accidents at Allis-Chalmers. Ann Stresau (charts & tables)..Dec. 20—114
Titanium fasteners: planemakers pool technology to improve them. Aug. 30—128
University of Michigan Industrial Program will inform industry of latest accomplishments .....Oct. 25—178

Rivets and Riveting:

Film-index system controls riveting machine at Convair .....July 19—160
Kick-press speeds rivet-cutting. S. Wencek (P.I.) .....June 7—157
Riveting hammer drives nails to depth. G. Collinson (P.I.).....Jan. 4—118

Roll flowing—New concept in plastic deformation saves operations and conserves materials. C. L. Sporck.....Mar. 29—104

Rollers:

Adjustable rollers speed corrugation forming. H. Dahl (P.I.)....June 7—159
Anti-friction holder aids thread rolling. Fred Buehler (P.I.) .....Oct. 11—175
Ball-bearing fixture rolls out copper wire. M. Barash (P.I.).....Apr. 26—139
Beryllium requires special rolling methods. Shields M. Bishop (report) Apr. 12—207
Shop-made sheet metal rolling machine. Bert Goldrath (P.I.).....July 19—148

Spline rolling (cover).....June 21— 2

Round Table:

Jan. 4—115, Feb. 1—112, Feb. 15—157, Mar. 1—121, Mar. 15—149, Mar. 29—114, Apr. 12—212, Apr. 26—135, May 10—167, May 25—145, June 7—153, June 21—141, July 5—145, July 19—141, Aug. 2—133, Aug. 16—141, Aug. 30—100, Sept. 13—137, Sept. 27—128, Oct. 11—169, Oct. 25—157, Nov. 22—145, Dec. 6—161, Dec. 20—113

Rubber—Slicing knives help cut soft rubber roll. M. Barash (P.I.) ...Oct. 25—161
Sponge rubber solves grinding problem. Jack Finlay (P.I.).....July 19—146

Russia:

Automation applied to 20-year-old machines. David Scott .....Oct. 11—164
Ceramic-tipped tools will cut steel—Russian report. (tables).....Nov. 22—113
Giant plano-miller .....Oct. 11—195
Induction forges replace hammers. Aug. 30—130
Machine tool progress for Russia at Leipzig Fair .....Oct. 11—192
New concept of cutting tools. Frank Sachs (charts) .....Apr. 12—170
Note from Moscow (ed).....May 10—119
Plastic mass for actuating medium harnessed by Russians.....June 21—126
Soviet challenge in productivity (ed). Mar. 1— 95
Trade with Russia: the lid is off on 30% of once banned metalworking equipment .....Sept. 13—198

Rust preventive—Camphor prevents rust on small tools. R. Isetts (P.I.)...Mar. 29—129

S

Safety:

Circular parallels of steel pipe and tubing to avoid accidents. Henry George (P.I.) .....Aug. 2—137
Magnetic parallels for safer repairs. Henry George (P.I.).....Oct. 11—174
Personal interest and guards . . . cut accidents, boost production. C. L. Morgan .....Sept. 13—178
Press overloading safety device. F. Strasser (P.I.) .....Dec. 20—120
Risk of accidents eliminated with manual hoist. Oscar Wittlinger (P.I.) Oct. 11—173
Temperature has nothing to do with accident rate. Ann Stresau (charts & tables) .....Dec. 20—114
Why . . . production-wise, plant-protection foolish? W. K. Ousley May 24—146
Will 100% safety glasses work? Oct. 25—123

Salvage:

Boeing Airplane salvage parts of pinball machines .....Sept. 13—169
Diamond sludge salvage .....Aug. 16—121
Eaton has tool-care program to reduce wastage of carbide tools .....Sept. 27—160
Hard chrome plate pays unexpected dividends. White & McKean.....Aug. 16—142
Old Masters' touch salvages scrap parts July 5—119
Trepan bottoming holes in one operation. R. W. Holmes .....Aug. 16—120
Trepanning titanium saves time and material. Siemen & Rosato .....Aug. 30— 89

Saugus Iron Works—Museum opened .... Sept. 27—159

Saws and Sawing:

Alcoa's bandsaw (cover) .....Dec. 6— 2
American Machinist production nuggets of machining .....Mid-Nov.—B1-37
Bandsaw work improved by scales. J. N. Schwartz (P.I.).....Apr. 12—216
Carbide inserts on bandsaw guide. J. J. Fitzgerald (P.I.) .....Dec. 6—172
Half-twist helps match butt ends of saw blades. H. J. Gerber (P.I.) Mar. 15—167
How to machine acrylic plastics. Dr. O. L. Pierson (report) (tables) .... Feb. 1—113-120
Improvised "slotting machine" speeds work on plates. Clifford Molloy (P.I.) May 10—176
Steel rollers aid bandsaw work. C. R. Cook (P.I.) .....May 10—173

Scales:

Scale speeds bandsaw work. J. N. Schwartz (P.I.) .....Apr. 12—216
Simple scale measures compression and tension. Chris Stougaard (P.I.).... Apr. 26—137

"Scrabble"—appropriate cover for Production Preview issue (cover) ..... Jan. 18— 2
Scrap—Tapered "horns" eliminate strippers. F. E. Chace (P.I.) .....Dec. 6—175
Screwdrivers—Knurled screwdriver blade. J. Zilch (P.I.) .....Oct. 25—162

Screw Machines:

Gun-drilling on converted screw-machine. W. M. Stocker, Jr. .....Feb. 15—162
Stock cutting speeded with modified screw machines. Henry George (P.I.) Jan. 4—120
Stopping-disk insert saves setup time. Mike Zmunda (P.I.).....Sept. 13—184

Screws—Lockscrews—use cotton to avoid damage to threads of bolt. G. R. Milner (P.I.) .....Dec. 20—117

Scribers:

Adjustable scriber simplifies vernier height gage settings. R. H. Fry (P.I.) .....Aug. 16—147
Needle bearings used for scribers. Roger Isetts (P.I.) .....Feb. 15—165
Titanium scriber marks lines on glass. J. M. Heath (P.I.) .....Mar. 1—125

Sealing—Sealing wax saves lapping job. Ralph Conklin .....Apr. 12—214
Seismograph places grinders (chart) Apr. 12—209
Selling—ready to make the most of it? (ed) Jan. 4— 87
Shafts—How Britain machines big diesel crankshafts .....Mar. 15—158

Shapers:

American Machinist production nuggets of machining (charts & tables) Mid-Nov. B1-37
Attachment to shaper cuts hand work on punches. H. Gifford (P.I.) ..Feb. 15—166
Gear-cutting savvy in 16 easy steps. R. S. Hildreth .....Mar. 29— 99
Hot extrusion of steel and titanium shapes .....Apr. 12—256
Ratchet speeds shaper work. Clifford Molloy (P.I.) .....July 19—145
Roll flowing, Floturn process, saves operations and conserves materials. C. L. Sporck .....Mar. 29—104
Rotating toolholder shapes die openings. Henry Gifford (P.I.).....Mar. 1—126
Shaper attachment generates bevel gears. Haim Murro .....Mar. 1—122
Surface grinding with shaper. Gurbachan Singh (P.I.) .....Dec. 6—173

Sharpe, Henry D.—dies—headed B&S 52 years .....June 7—181
Sharpening—Fixture sharpens milling cutters on lathe (P.I.) .....Aug. 2—137
Shavers—gear-cutting savvy in 16 easy steps. R. S. Hildreth .....Mar. 29— 99

Shears and Shearing:

Devices eliminate shear pins. W. C. Betz (P.I.) .....June 21—148
Gear-cutting savvy in 16 easy steps. R. S. Hildreth .....Mar. 29— 99
Simple rotary shear on lathe. H. J. Gerber (P.I.) .....July 5—152
Slide attached to shear catches workpieces. M. Yamaguchi (P.I.).Mar. 15—166

Shells:

Ball-bearing locks on fixture aid turning of ordnance shells. D. G. Nolle (P.I.) .....May 24—132
Cope talks on draw dies. S. R. Cope
Pt. 8 Wide-flanged shells draw easily if you follow the rules ... Jan. 4—100
Pt. 9 Know the wrinkles about spherical shells .....Feb. 15—148
Pt. 10 Reverse drawing gives you greater reductions ... Mar. 15—134
Pt. 11 Observe 6 rules when making tapered shells .....Apr. 26—114
Pt. 12 Tapered shells require skillful operation layout ... May 10—168
Pt. 13 Iron shells to get accurate diameters or smooth finish ... June 7—134
Pt. 14 Three shell jobs typify ironing operations .....July 5—126
Pt. 15 Necked shells require careful reduction .....July 19—130
Pt. 16 Make offsets in dies or on lathes Aug. 2—134
Pt. 17 Choose from 4 methods to bulge shells .....Aug. 16—122
Pt. 18 Fluid dies bulge shells and form ornamental designs Aug. 30—109
Pt. 20 Choice of die type depends on the burr .....Sept. 27—120
Pt. 22 Make small shells in progressive dies .....Dec. 20— 94

Is shell molding practical for job lots? F. K. Shallenberger (table) Oct. 25—130
Three leaf springs support thin-walled redraw work. Charles Schwartz (P.I.) Apr. 26—140

Shims—Cut costs with die-shim perforators. I. G. Schlindwein .....Sept. 27—123
Tapered shims aid grinding die clearances. A. Jonas (P.I.).....Oct. 11—176

Shop shots
Mar. 15—150, May 24—116, Sept. 13—170, Sept. 27—126, Oct. 11—170, Oct. 25—124, Dec. 6—132

Silver—Brazing goes automatic. Spiesz & Leuthner .....May 10—121
Sine square—Knife-edged for easy layout. Jack Dalton (P.I.) .....Nov. 22—150
Slotters and Slotting—Chart for slotting-cutter runout. D. E. Sweet (chart) (Ref. Bk. Sheet) .....Sept. 27—151
Curved slots are drilled and cut in a timesaving method. H. P. Kunkleman. Aug. 2—110

Society of Automotive Engineers—National Production Meeting of SAE discusses automation .....Apr. 12—258

Solders and Soldering:

How to nickel-plate aluminum for solder joining. W. M. Stocker, Jr.....June 7—154
UHF contacts for electronic oscillators formed four times faster. C. S. Selby Feb. 1— 97

(ed) Editorial (P.I.) Practical Ideas

Speeds:
Cool tip . . . not chip, with CO_2—new English technique increases cutting speed . . . . . Feb. 15—130
Feeds and speeds for turning steel (Ref. Bk. Sheet) (charts) . . . . . Dec. 6—183
Output shaft of differential controls speed from 0 to 300 RPM. Chris Stougaard (P.I.) . . . . . Mar. 1—127
Thermal number measures efficiency of metal cutting. K. J. Trigger (report) (charts) . . . . . June 7—145-152
Spinning—Spin re-entrant shapes of low melting alloys. Sams & Borodavchuk . . . . . Feb. 15—145
Spotfacing—In-place babbitting aids spotfacing large casting. J. H. Rollin (P.I.) . . . Mar. 15—164

Springs:
Auxiliary spring makes safer surface grinders. W. C. Betz (P.I.) . . Mar. 15—164
Endless coil spring activates stripper fingers. Burnett Menkin (P.I.) Apr. 12—213
Etching weakens springs to specifications. Haim Murro (P.I.) . . . . . Feb. 1—125
Formula aids spring-winding. F. Strasser (P.I.) . . . . . June 7—160
Press-replacement study pays off for spring maker. J. R. Nikolais Dec. 20—130
Spherical seats aid die spring application. F. E. Elmo (P.I.) . . . . . July —152
Sprockets—Bicycle sprockets help small crane move freely. B. Goldrath (P.I.) June 7—158
Staking—Split-bushing fixture simplifies staking. E. G. Filipowicz (P.I.) . . . . Feb. 15—165

Stamping:
Artists sculpture mica dies. J. P. Wright (charts & tables) (report) . . . . . Sept. 13—145-160
Cope talks on draw dies. S. R. Cope
Pt. 19 Stampings often require burred or flanged holes . . . . . Sept. 13—140
Pt. 22 Make small shells in progressive dies . . . . . Dec. 20— 94
Good tooling plus dial feeds will cut stamping costs. W. W. Schug . . . . . Oct. 11—129
Pressed Metals Institute discusses metal stampings outlook . . . . . Dec. 6—193
Sound-color film "Stampings for Electronics" on free loan to industry . . . . . July 5—164

Standardization:
American Gear Mfrs Assn. announces new gear standards . . . . . Nov. 8—182
Leipzig Fair—standardization characterizes communist-built machine tools. David Scott . . . . . Feb. 15—158
Limits and fits for cylindrical parts (Ref. Bk. Sheets) Pts. 1, 2 & 3 July 19—151; Pts. 4, 5 & 6 Aug. 2—143; Pts. 7, 8 & 9 Aug. 16—151; Pts. 10 & 11 Aug. 30—119
Marking of compressed-gas containers. F. R. Fetherstone (Ref. Bk. Sheet) Sept. 13—191
Measured toolroom time standards have been successfully used for the past ten years. R. M. Crossan (tables) Sept. 27—113

Steel:
Australia reports severe steel shortage Oct. 11—195
Boeing develops scale-inhibiting treatment for titanium and stainless . . . . . Aug. 30—112
Free machining tool steels: yes or no? June 7—175
Hot extrusion of titanium and steel shapes . . . . . Apr. 12—256
Hot rolling mill speeds output of specialty steels . . . . . Dec. 6—190
Hot-spinning stainless (cover) . Sept. 27— 2
How to work stainless steel. R. E. Paret (tables) (report) . . . . . Sept. 27—129-140
How to work steel. Ashburn & Le Grand (charts & tables) (report) . . . . Mid-Nov.—33-160
Jet cooling triples feed rate on plunge and thread grinding of tool steel Rc62-64 (charts) . . . . . Jan. 4—137
Pittsburgh Steel opens sheet mill . . . May 10—192
Speeds and feeds for turning steel (Ref. Bk. Sheet) (charts) . . . . . Dec. 6—183
Thermonol, new miracle alloy, can replace stainless . . . . . Mar. 15—182
Stops—'Flying stop' shows drill cutting action. C. J. Oxford, Jr. . . . . Mar. 1—102
Straightening—Hardwood boards straighten small tubes. Edward Smalenberger (P.I.) May 24—149
Stretching aluminum plate to reduce machining distortion. Lawler & Binkley (tables) Mar. 15—128

Strippers:
Endless coil spring activates stripper fingers. Burnett Menkin (P.I.) Apr. 12—213
Lock-washer strip-stock fed through stripper. Hjalmar Dahl (P.I.) Aug. 2—140
Lucite stripper for locating nameplates. V. Stuart (P.I.) . . . . . Aug. 30—113
Tapered "horns" eliminate strippers. F. E. Chase (P.I.) . . . . . Dec. 6—175
Studs—Cutoff table extended. W. Hartmann (P.I.) . . . . . Dec. 20—120
Threaded stud aids tapered reamer. Max Karfunkel (P.I.) . . . . . Dec. 6—175
Subcontracting—How to coordinate subcontracting to meet production schedules. G. E. Fouch (report) (charts) . . . . . Feb. 15—137-144
Suggestion plans—What makes them work? V. H. Rotroff . . . . . July 19—144

Switches:
Holes pulverized in plastic switch bodies. A. L. Levitt . . . . . Oct. 11—144
Limit switches gage centers in high production. J. W. Farrell (P.I.). Nov. 22—151
Precision limit switches for production gaging. S. Kopacz (P.I.) . May 24—152
Side cams on assembly die speed switch assembly. Federico Strasser (P.I.) Aug. 16—145

T

Tables:
Disconnected table worm speeds alignment. Gustav Wernberg (P.I.) Feb. 1—126
Special table and vacuum chuck increase milling machine range. R. W. Holmes (charts) . . . . . Apr. 12—210
Stud extends cutoff table. W. Hartmann (P.I.) . . . . . Dec. 20—120
Talented Tooling . . . . . Aug. 2—112
Tangents by Tange . . . . . Mid-Nov.—C40-59

Tanks (Military):
Chrysler-Run Michoud tank plant is largest to go standby . . . . . Sept. 13—199
Ford Motor mothballing tank-building equipment . . . . . May 24—166
Production shortcuts help power tanks. G. H. DeGroat . . . . . July 19—122
Tapers and Tapering—Guided ring checks tapers. W. I. Morgan (P.I.) . . Mar. 29—129
Inexpensive gage helps match tapers. Carl Jensen (P.I.) . . . . . Feb. 1—124

Taps and Tapping:
American Machinist production nuggets of machining (charts & tables) . . . . Mid-Nov.—B1-37
Hand tapping angle iron speeded with "brace and bit." George Koslow (P.I.) Jan. 4—116
Removing broken drills and taps. L. R. Choudhary (P.I.) . . . . . Jan. 4—116

Taxation:
New tax laws give U.S. business a break on depreciation . . . . . Aug. 15—168
New U.S. tax laws and metalworking (charts) . . . . . Sept. 13—194
Our "enlightened" tax policy (ed) . . . . June 7—127
Realistic depreciation rates. Burnham Finney (report) (chart) . . Mar. 1—113-120
Used machinery: will taxes rock the boat? . . . . . May 10—196
What are you doing about depreciation? (ed) . . . . . Sept. 27—111
Telephones—Conveyors and telephones speed schedules. W. A. Ring . . . . . Sept. 13—134
Television—Color TV sets cost Westinghouse $3000 for a set that retails for $1295. Mar. 29—140
Templets—Interchangeable templets diversify drill jig. L. H. Austin (P.I.) Mar. 1—128
Tilted templet reproduces correct form for milling. H. K. Fronicke (P.I.) Jan. 4—119

Testing:
Aluminum ingots for AF heavy presses test forged . . . . . July 19—164
American Machinist production nuggets of inspecting, testing, quality control . . Mid-Nov.—E1-5
'Flying stop' shows drill cutting action. C. J. Oxford, Jr. . . . . Mar. 1—102
Hydraulic oil is employed in testing pumps and valves for power steering units. J. A. Hudson . . . . . Aug. 30— 92
Industrial betatron for radiographic examinations at Detroit Arsenal . . . . Aug. 16—160
Wildhaber formulas tested . . . . . July 5—166
Thermal number—Measures efficiency of metal cutting. K. J. Trigger (report) (charts) . . . . . June 7—145-152
Thermond—New miracle alloy can replace stainless . . . . . Mar. 15—182

Threads and Threading:
American Machinist production nuggets of machining (charts & tables) . . . . Mid-Nov.—B1-37
Anti-friction holder aids thread rolling. Fred Buehler (P.I.) . . . . . Oct. 11—175
Brass threading. M. Barash (P.I.) . . . Dec. 20—119
Chart for threading time. T. Hicks (Ref. Bk. Sheet) . . . . . Mar. 1—135
Conversion capers speed threading and drilling. A. G. Gould . . . . . Dec. 20—109
Fastening ring nut to a threaded shaft. G. R. Milner (P.I.) . . . . . Oct. 11—173
Formula aids cutting double lead threads. H. W. Holmdahl (P.I.) . . . . . Jan. 4—117
Formula for multiple-lead threads speeds shop calculating. H. W. Holmdahl (P.I.) . . . . . Oct. 25—164
Knurling simplified with lightly cut screw thread. M. Barash (P.I.) Feb. 1—127
Nomograph aids solution of worm-thread profiles. O. Saari (charts & tables) . . . . . July 5—113
Normal thread angles and bottom flats (Acme) Donald Sweet (tables) (Ref. Bk. Sheets) Pts. 1 & 2 . . . . Sept. 27—147
Self-opening dieheads cut threading time. W. D. Arnot (P.I.) . . . . . July 5—151
Slot in thread cleans bolts. C. L. Martin (P.I.) . . . . . Mar. 1—128
Stripped threads in magnesium castings replaced by wire-thread inserts Mar. 1—105
Threaded arbor saves straddle-mill setup time. Henry George (P.I.) Apr. 26—138
Threaded die put threads on sheet metal. John Muth (P.I.) . . . . . Apr. 12—216
Threaded plug starts cut at correct radial position. J. Stewart (P.I.) . . . Feb. 15—168
Tolerances for tap-drill holes (tables) (Ref. Bk. Sheets) Pts. 1, 2 & 3 . . . . Apr. 26—143
Turning and threading pipe ends for high-pressure couplings . . . . . Nov. 22—166

Time and Motion Study:
Minimum economical lot sizes. Tyler Hicks (Ref. Bk. Sheet) (chart) . . . . Feb. 15—171
Simple system streamlines job-shop operation. G. H. DeGroat . . . . . Sept. 13—176
Standard minutes . . . they work in the toolroom, too! R. M. Crossan (tables) Sept. 27—113
Tips for top shop men—June 7—144; July 19—132; Aug. 2—136

Titanium:
Aircraft designers replace heavy metal fittings and fasteners with titanium Aug. 30—128
Alloys center of interest at Metals show . . . . . Oct. 25—176
Belt grinding of titanium (Ref. Bk. Sheets) (charts) Pts. 1, 2 & 3 June 7—163
Boeing develops scale-inhibiting treatment for titanium and stainless . . . . Aug. 30—112
CO_2 concept machines titanium alloys and heat-resistant materials. G. H. DeGroat . . . . . Aug. 2—152
Conventional tools machine titanium. Roland Satterlee . . . . . Aug. 30— 94
Cratering main cause of tool failure in machining titanium . . . . . Feb. 15—147
Engineers talk new tooling at Purdue June 7—172
Furnace-brazing of titanium (charts) . . Aug. 16—117
Grinding titanium no longer a problem. E. J. Krabacher (charts & tables) . . June 21—124
Hot extrusion of titanium and steel shapes . . . . . Apr. 12—256
How Rohr heats dies to form titanium. J. E. Rheim . . . . . Oct. 11—161
How Ryan forms and welds titanium Dec. 6—138
Machining ti-stainless. George Glaeser . . Sept. 13—144
Machining titanium with coolants (Ref. Bk. Sheets) (charts & tables) Pts. 1, 2 & 3 . . . . . May 24—155
Republic Aviation's new drill angles for titanium . . . . . June 21—142
Shop hints help form and mill titanium Sept. 13—129
Spotwelding 6-in. titanium stack. May 24—163
Spot welds work well in titanium. Begeman & McBee (charts & tables) . . Dec. 20— 98
Trepanning titanium saves time and material. Sieman & Rosato . Aug. 30— 89
Unorthodox when machined . . . here's why. M. E. Merchant & others (charts) . . . . . July 5—118

Tolerances:
Adjustable scriber simplifies vernier height gage settings. R. H. Fry (P.I.) Aug. 16—147
Gear-hob tolerances. H. V. Gregg (Ref. Bk. Sheets) (tables)
Pts. 1 & 2 . . . . . Nov. 22—157
Pts. 3 & 4 . . . . . Dec. 6—179
Hard chrome can be plated to tolerances within "tenths" in production. George DeMirjian (chart) . . . . . Aug. 2—101
Offset compound eases work in close tolerances. A. F. Roses (P.I.) . . Feb. 1—127

(ed) Editorial (P.I.) Practical Ideas

Tolerances for tap-drill holes (tables) (Ref. Bk. Sheets) Pts. 1, 2 & 3 ... Apr. 26—143

Toolholders:

Adjustable toolblocks speed setups. A. G. Gould (P.I.) ..... Sept. 13—183
Air speeds control-device assembly. D. S. Lisberger ..... Aug. 16—126
Boring bar holder. H. N. McAllister (P.I.) ..... July 19—147
Double-toolholder aids cutting of oil grooves. Clifford Molloy (P.I.) Apr. 12—216
Flexible tool support aids cutting tapered hole. J. W. Wallace (P.I.) ... July 5—150
Floating reamer-holder for knee tools. D. Moore (P.I.) ..... Aug. 30—116
Guided tool in offset holder aids turning OD of large hub. G. H. Rogers (P.I.) ... Nov. 22—149
Hinged toolholder planes parallel grooves. H. M. Mason (P.I.) Sept. 13—181
Honeycomb fixture holds rings flat during quenching. E. Taylor (P.I.) ... Aug. 16—146
Hose clips do variety of emergency jobs. W. D. Arnot (P.I.) ..... Feb. 1—125
Pinion-drive turns cone taper. Manohar Lal (P.I.) ..... Dec. 6—176
Rotating toolholders shapes die openings. Henry Gifford (P.I.) ..... Mar. 1—126
Shop-made "music stands" hold blueprints (P.I.) ..... Aug. 30—116
Slotted toolholder makes offhand grinding safer. T. A. Fitzgerald (P.I.) .. Mar. 29—129
Special tools support 14,000-ton extrusion press. W. C. Winter (table) ... Dec. 6—162
Tubing cutoff method. A. I. Levitt (P.I.) ... Aug. 16—148
Type-holder in chuck speeds marking round workpiece. Robert Carr (P.I.) ... Oct. 25—162

Tooling—American Machinist production nuggets ..... Mid-Nov.—C1-13

Tools:

ASTE tool show highlights ..... May 10—186
American Machinist production nuggets of assembling, welding, portable tools (chart) ..... Mid-Nov.—F1-15
American Machinist production nuggets of tooling ..... Mid-Nov.—C1-13
Checking tool design. C. Bossman ... Oct. 11—140
Difference curves solve form-tool corrections. Oliver Saari (Ref. Bk. Sheets) (charts & tables) Pts. 1, 2 & 3. Mar. 15—171
Dixieland style tool show ..... June 7—177
DoAll's "Civilization through tools" caravan tours industrial America ... Nov. 22—162
Free machining tool steels: yes or no? ... June 7—175
Gisholt to lease machine tools. June 7—175
Hot machining cell at Oak Ridge (cover) ... Apr. 12— 2
How to braze, grind, and inspect carbide-tipped tools (Ref. Bk. Sheets) ... Dec. 20—123
How tools made the world in which we live. E. J. Tangerman (flowsheet) (report) ..... Dec. 20—101-108
New equipment at tool show ... Apr. 12—217
New plan for government tools Dec. 20—134
New tools for the planemaker to fit jet age machining problems ..... Dec. 6—192
1954 Tool Show ..... Apr. 12—250
Robot-run tools machine "hot" materials at Oak Ridge. S. E. Dismuke (charts) ... Apr. 12—161
Russian design for cutting edge of single-point tools. Frank Sachs (charts) ... Apr. 12—170
Tool lease pros and cons ..... Apr. 12—252

Training:

Apprentice training program for diemakers at Schneider & Marquard. J. P. Wright (charts & tables) (report) ..... Sept. 13—145-160
Get returns from foreman training. G. S. Odiorne ..... Dec. 6—137
Supervisors for tomorrow. W. M. Stocker Jr. (report) ..... Aug. 16—133-140
Tool and diemakers trained at John Volkert Metal Stampings ... Apr. 26—156
Why "shop" courses in college? E. W. Dunlap ..... Mar. 1—100

Transfer machines—Pre-positioned setups speed job-lot production ..... Dec. 6—142

Trepanning:

Bottoming holes in one operation. R. W. Holmes ..... Aug. 16—120
High-speed trepanning. W. M. Stocker, Jr. (report) ..... Jan. 4—105-114
Special cutting heads finish 1066 holes. Carl Jensen (P.I.) ..... May 10—173
Time and material saved by trepanning titanium from solid billets. Siemen & Rosato ..... Aug. 30— 89

Tubing:

Ball-bearing tube-driver for rough ID, finished OD. A. Fischer (P.I.) ... Feb. 15—165
Biggest aluminum drawn tubes? That's what England's James Booth & Co. claims ..... Aug. 16—161
Hardwood boards straighten small tubes. Edward Smalenberger (P.I.) May 24—149
How to bend aluminum tube and bar (report) J. M. Adle ..... May 24—137-144
Pattern of tubing from a single sheet of metal ..... Nov. 8—178
Soft die and hard arbor taper tubes. F. E. Chase (P.I.) ..... Sept. 27—141
Tailstock attachment aids aluminum tube cutoff. H. Koslow (P.I.) ... May 10—175
Welding tubular parts are automatically. Roy Martin ..... Sept. 27—119

Turbines:

Gas burners braze turbine blades. E. M. Miekley ..... Dec. 6—170
Gas turbines for US Navy ... Aug. 30—132
Regenerative gas turbine developed by Chrysler Corp. ..... Apr. 12—259

Turning:

Floturn, new concept in plastic deformation, saves operations and conserves materials. C. L. Sporck ..... Mar. 29—104
Flow turning, new metalworking process (cover) ..... Mar. 29— 2
Guided tool in offset holder aids turning OD of large hub. G. H. Rogers (P.I.) ..... Nov. 22—149
Turning and threading pipe ends for high-pressure couplings ..... Nov. 22—166

Typewriters—type segments are made with ultrasonics. E. J. Tangerman .. Aug. 30— 85

U

Ultrasonics:

Guided missiles: is technical cloak-and-daggerism hiding a snafu? ... July 5—162
Production problems on supersonic planes. A. Ashburn (report) ..... July 5—129-144
Work cuts tool, tool forms work . . . with ultrasonics. E. J. Tangerman ... Aug. 30— 85
Ultrasonic machining (cover) ... Aug. 30— 2

U.S. Air Force:

Heavy press program gets underway at Alcoa, Lafayette ..... June 7—173
Pick-a-back tooling machines forgings for giant press. W. M. Stocker, Jr. ... July 19—117
Wind tunnel at Tullahoma, Tenn.—a problem in huge construction. G. H. Heiser ..... July 19—142

V

Valves—Testing pumps and valves for power steering units. J. A. Hudson .Aug. 30— 92
Tool steel milling inserts machine valve faces. Carl Jensen (P.I.) ... Dec. 20—119

Vance Plan: is the Pentagon putting roadblocks in its way? ..... Mar. 29—140

Vibrations—Dynamometer vibrations dampened with dashpot. Oliver Saari (P.I.) ... Jan. 4—116

Vises:

Handwheel-hub device to lock vises. G. H. Koslow (P.I.) ..... Apr. 26—139
Simple device gages vise-held work. Jaan Wain (P.I.) ..... Oct. 25—164
Tray on vise saves wear on slide. Fred Lettino (P.I.) ..... Oct. 25—161
Workholding devices handbook. H. E. Linsley (report) Pt. 2 Stationary devices ..... Oct. 11—145-160

W

Washers — Lock-washer strip-stock fed through stripper. Hjalmar Dahl (P.I.) ... Aug. 2—140

Wear of Tools:

Cratering main cause of tool failure in machining titanium ..... Feb. 15—147
Foam-cooling method increases tool life and improves work conditions. Mason & Weber (chart) ..... Apr. 12—174
Reasons for carbide-tool failure. W. L. Kennicott (Ref. Bk. Sheets) Pts. 1, 2 & 3 ..... June 21—159 Pts. 4, 5 & 6 ..... July 5—155
Shorter chipbreakers have diamonds. W. A. Fanger ..... May 24—113

Welding:

American Machinist production nuggets of assembling, welding, portable tools (chart) ..... Mid-Nov.—F1-15
Automatic welding fixture eliminates need for costly positioning. Troyer & Lorain Jr. (chart) ..... Apr. 26—108
Bandsaw welder butt-welds small drill extensions. Joseph Mate (P.I.) ... May 10—174
Butt ends of saw blades half-twisted for matching. H. J. Gerber (P.I.) Mar. 15—167
Contour welding performed automatically ... Feb. 1—107
Engineers talk new tooling at Purdue ... June 7—172
Gas-welding hard surfaces for precision. John Wischhusen ..... May 24—126
How Ryan forms and welds titanium ... Dec. 6—138
Simple clamping device holds channels for welding. Franz Eheim (P.I.) ... Feb. 1—126
Spot welding aluminum (Ref. Bk. Sheet) (chart & tables) Pts. 1, 2 & 3 ... Jan. 4—123
Spotwelding 6-in. titanium stack. May 24—163
Spot welds work well in titanium. Begeman & McBee (charts & tables) ... Dec. 20— 98
Tantalum and columbium properties and methods of working. J. W. Rose (report) (charts & tables) .... Apr. 12—189
Tubular parts are welded automatically. Roy Martin ..... Sept. 27—119
Welding 6½ in. steel ..... Mar. 15—182
Westinghouse produces two refrigerators a minute with integrated production, automatic welding. G. H. DeGroat ..... May 10—157

Wheels:

Contact wheels influence abrasive-belt performance ..... June 21—121
Crush-dress grinding wheels for centerless-grinding of parts of plastic and wood rod. Gentile & Schaper .. May 10—134
Mounting cylindrical grinding wheels (Ref. Bk. Sheet) ..... Apr. 12—243
Take your pick of a million grinding wheels. N. P. Robie (tables) ... Aug. 2—114

Wind Tunnels—Blading and balancing compressor disk for USAF's propulsion wind tunnel ..... Aug. 2—155
U.S. Air Force wind tunnel—a problem in huge construction. G. H. Heiser ... July 19—142

Wire:

Bench tool knurls piano wire. E. F. Siebold (P.I.) ..... Aug. 2—139
Elliptical "spaghetti" simplifies wiring. G. Collinson (P.I.) ..... Feb. 15—165
Spring wire aids checking depths. Robert Roedder (P.I.) ..... Apr. 12—213
Simple wire-bending die. Federico Strasser (P.I.) ..... June 21—147

Wood—How to centerless-grind parts of plastic and wood rod. Gentile & Schaper ..... May 10—134
Jigs and rigs cut densified wood Nov. 22—147

Wrenches:

Brazing lathe wrenches for convenient use. Joe Dalton (P.I.) ..... Jan. 4—120
Ratchet speeds shaper work. Clifford Molloy (P.I.) ..... July 19—145
Self ejecting chuck wrench. H. F. Ross (P.I.) ..... Sept. 27—142
Spanner wrench avoids chuck damage. Richard Cataldo (P.I.) ..... Apr. 26—136

Z

Zirconium—Shop practice (report) .. Apr. 12—199

AUTHOR'S INDEX

ADAMS, WILLIAM If worn file handles have to be repaired in a hurry Apr. 26—137
Laundry soap cuts heat scale Mar. 29—130
Washer cutter forms emergency belts Jan. 4—119
Adle, J. M. How to bent aluminum tube and bar May 24—137
How to stretch-form aluminum July 19—133
Aljanich, Matt Caterpillar hollow-grinds clamped carbide tips Jan. 4— 89
Amos, A. G. Adjustable go-no go id gages Sept. 27—141
Anderson, B. H. & Dr. N. W. Thibault Why line your sludge tank with diamonds? Feb. 15—154
Arnold, S. V., A. R. Kaufman & P. L. Lowenstein Beryllium — next wonder metal? Apr. 12—203
Arnot, W. D. Hose clips do variety of emergency jobs Feb. 1—125
Self-opening dieheads cut threading time July 5—151
Ashburn, Anderson Carbide cuts carbide chipbreakers when Watertown Arsenal puts electrical-discharge machining on a production basis Apr. 12—185
Production problems on supersonic planes July 5—129-144
Ashburn, Anderson & Rupert Le Grand How to work steel Mid-Nov.—33-160
Austin, Laurence H. Hinged spacers aid milling flats Nov. 22—152
Interchangeable templets diversify drill jig Mar. 1—128
Paper makes magnet easier to use. Aug. 2—138

BARASH, M. Ball-bearing fixture rolls out copper wire Apr. 26—139
Slicing knives help cut soft rubber roll Oct. 25—161
Spring-and-V-block fixture aids drilling small shafts May 10—175
Stepped plates aid mike reconditioning Mar. 15—168
When threading brass Dec. 20—119
Begeman, M. L. & Frank W. McBee Spot welds work well in titanium Dec. 20— 98
Behrend, Ralph H. Small hydraulic presses do yeoman work Oct. 25—126
Betz, William C. Auxiliary spring makes safer surface grinders Mar. 15—164
Devices eliminate shear pins June 21—148
Biechele, Frank Check list for machine care Feb. 1—135
Binkley, V. F. & W. J. Lawler Stretch aluminum plate to reduce machining distortion Mar. 15—128
Bishop, Shields M. Beryllium requires special rolling and forging methods Apr. 12—207
Bittern, J. E. Pivoted cutter forms oil grooves Feb. 15—166
Boehnlein, Edward P. Die-setter's manual Pts. 1, 2 & 3 Nov. 8—167; Pt. 4 Nov. 22—155
Borodavchuk, Joseph & Denver Sams Spin re-entrant shapes Feb. 15—145
Bossman, Clifford. Coated wheel on V-block aids concentricity check May 24—150
Equalizing clamp for light work June 21—148
Tool design checker . . . balance wheel or brake? Oct. 11—140
Bowman, Gilbert J. Double-acting pressure pad aids part ejection Jan. 4—117
Cam-operated air cylinder for rapid part ejection Feb. 1—124
Brash, M. Lightly cut screw thread simplifies knurling Feb. 1—127
Braun, Leo Radial drills make chips by the ton May 24—148
Brenner, Morris Production methods are key to improved bolt design July 5—146
Brosheer, Ben C. Synchromation speeds output of standard machines Dec. 20—110
Brown, James Sound tooling simplifies tough progressive die Nov. 22—142
Bryant, Robert "Snorkel" cools deep tapping job Oct. 25—161
Budwitz, P. L. Drill chuck adapter for tailstock June 21—148
Buehler, Fred Anti-friction holder aids thread rolling Oct. 11—175
Burns, J. R. How abrasive-belt grinding improves taper sheet production. Nov. 22—126

CARR, ROBERT Type-holder in chuck speeds marking round workpiece Oct. 25—162
Cataldo, Richard Special spanner wrench avoids chuck damage Apr. 26—136
Cerullo, Ottavio Plate-glass extension adds capacity to comparator May 10—174
Cervelli, Peter In-place-machined pivot pin saves downtime of crane Apr. 26—138
Chace, F. E. Tapered "horns" eliminate strippers Dec. 6—175
Soft die and hard arbor taper tubes. Sept. 27—141
Chattacharyya, A. C. Simple gage measures large radius Dec. 6—174
Choudhary, L. R. Another method for removing broken drills, taps Jan. 4—116
Soft iron cylinder holds end mill. Feb. 1—128
Clarke, Allan Plunge cut and helix produce boring tool Mar. 29—130
Coates, Jerry "Dieset comparator" easily made from stock parts Oct. 11—175
Collinson, G. Elliptical "spaghetti" simplifies wiring Feb. 15—165
Riveting hammer drives nails to depth. Jan. 4—118
Colvin, Fred H. Modern metalworking in Mexico Aug. 2—104
Conklin, Ralph Sealing wax saves lapping job Apr. 12—214
Cook, George F. Steel rollers aid bandsaw work May 10—173
Cook, N. H., E. G. Loewen & M. C. Shaw Machine-tool dynamometers . . . a current appraisal May 10—125
Cope, Stanley R. Cope talks on draw dies Pt. 8 Jan. 4—100, Pt. 9 Feb. 15—148, Pt. 10 Mar. 15—134, Pt. 11 Apr. 26—114, Pt. 12—May 10—168, Pt. 13 June 17—134, Pt. 14 July 5—126, Pt. 15 July 19—130, Pt. 16 Aug. 2—134, Pt. 17 Aug. 16—122, Pt. 18 Aug. 30—109, Pt. 19 Sept. 13—140, Pt. 20 Sept. 27—120, Pt. 21 Dec. 6—166, Pt. 22 Dec. 20— 94
Crossan, Richard M. Standard minutes . . . they work in the tooroom too! Sept. 27—113
Cunningham, J. B. Small shops can use automation too Apr. 12—177

DAHL, HJALMAR Adjustable rollers speed corrugation forming June 7—159
Lock-washer strip-stock fed through stripper Aug. 2—140
Redesigned bending die cuts one operation Jan. 4—119
Dalton, Jack Knife-edged "sine square" for easy layout Nov. 22—150
Dalton, Joe Brazing lathe wrenches for convenient use Jan. 4—120
De Angelis, Alfred. Air-cylinder attachment aids VTL contouring Dec. 20—116
DeGroat, George H. Big plant tooling in a small shop June 7—138
New CO_2 concept machines tough alloys Aug. 2—152
Production shortcuts help power tanks July 19—122
Simple system streamlines job-shop operation Sept. 13—176
Two refrigerators a minute May 10—157
DeMirjian, George Hard chrome can be plated to "tenths" in production. Aug. 2—101
Denst, Alexander A. Drum-lifting tongs handle pots of hot parts Oct. 25—163
De Pastina, R. & R. E. Eyre Automatic brushing deburrs turbine disks July 5—124
Dewick, Fred Fixture for castings with wrong draft angle Feb. 1—126
Dismuke, Stewart E. Robot-run tolls machine "hot" materials at Oak Ridge Apr. 12—161
Douglas, Edward Little dies lick big costs in short-run plastics Sept. 27—124
Duffy, Thomas H. Split cotter pins do variety of jobs June 7—157
Dunlap, Eugene W. Why "shop" courses in colleges? Mar. 1—100
Dunn, P. V. Another simple die change eliminates springback July 19—146
Simple die change cuts springback Apr. 26—137
Soft dowels in hard dies simplify die assembly Mar. 29—130

EDWARDS, R. K. Brass lifter aids undercutting in planer Mar. 15—168
Traverse one planer tool to cut radius with other tool Feb. 15—168
Eheim, Franz. Simple clamping device holds channels for welding Feb. 1—126
Elmo, F. C. Spherical seats aid die spring application July 5—152
Emerson, Charles D. How to control corrosion Dec. 6—145-160
Emerson, C. D. & W. M. Stocker, Jr. Numerical control, what it means to metalworking Oct. 25—133-156
Emrich, John "Tandem" drive mills keyway in large shaft Aug. 30—113
Engle, E. J. Try pleasing your boss Apr. 26—105
Epstein, Irving Improvised "sound locator" checks special machinery Feb. 15—167
Indexing head to mill square ends. Jan. 4—118
Eyre, R. E. & R. DePastina Automatic brushing deburrs turbine disks. July 5—124

FANGER, WAYNE A. Shorter chipbreakers save diamonds May 24—113
Farrell, Jack W. Limit switches gage centers in high production Nov. 22—151
Feinberg, N. Adapter corrects turret misalignment July 19—148
Fetherstone, F. R. Marking of compressed-gas containers Sept. 13—191
Feuerpfeil, W. G. Mist cooling helps some planer jobs Aug. 2—129
Filipowicz, E. G. Split-bushing fixture simplifies staking Feb. 15—165
Finlay, Jack Sponge rubber solves grinding problem July 19—146
Finney, Burnham. An "ace" insurance policy May 24—111
Automation is only the first step. Sept. 13—127
Better adapt yourself—or give up . . . Aug. 16—115
Better think it over, Mr. Reuther! Dec. 6—127
The boys from Syracuse point the way Feb. 1— 95
Co-determination Dec. 20— 87
Getting the most out of your machines Nov. 8—115
How long can the cycle last? Oct. 25—115
Invitation to disaster Oct. 11—127
Is automation your dish? Feb. 15—119
It's the people who count Mar. 15—119
It's time to adopt realistic depreciation rates to win the battle for modernization Mar. 1—113-120
Metalworking—1970 style Aug. 2— 99
No raids on machine tool reserves! Aug. 30— 83
Note from Moscow May 10—119
On behalf of more exports July 19—115
Our "enlightened" tax policy June 7—127
Ready to make the most of it? Jan. 4— 87
The remedy is not strong enough. Jan. 18—119
Replacement—market with a future June 21—115
Separating the men from the boys Nov. 22—111
Soviet challenge in productivity. Mar. 1— 95
Spring-clean your business (ed) Apr. 12—159
What are you doing about automation? July 5—111
What are you doing about depreciation? Sept. 27—111
What regularized replacement can do Apr. 26— 99
What the 50-plus club offers Mar. 29— 95
Fischer, Anton Ball-bearing tube-driver for rough ID, finished OD Feb. 15—165
Fitzgerald, J. J. Carbide inserts on bandsaw guide Dec. 6—172
Fitzgerald, T. A. Slotted toolholder makes offhand grinding safer Mar. 29—219
Friedman, Harry J. Pennies for photos save dollars in delay Dec. 6—134
Fristedt, A. E. Sawtooth steps make versatile clamp Oct. 11—172
Fronicke, H. K. Tilted templet reproduces correct form for milling Jan. 4—119
Fry, Charles Powered drillpress table speeds deep-hole work Sept. 13—182
Fry, R. H. Adjustable scriber simplifies vernier height gage settings Aug. 16—147
Fouck, George, E. How to coordinate subcontracting to meet production schedules Feb. 15—137-144

GEIGER, FRANK Stepped "gage table" aids form grinding Apr. 26—139
Gensler, J. K. Solenoid stops VTL ram feed July 19—147
Gentile, Charles & Leonard Schaper How to centerless-grind parts of plastic and wood rod May 10—134
George, Henry "Donuts" make good parallels Aug. 2—137
Extensions added to drillheads speed plate-drilling June 7—160
Graduations speed steadyrest setup Feb. 15—167
Jack removes arbors from drill chucks Mar. 1—128
Magnetic parallels for safer repairs Oct. 11—174
Modified screw-machines speed stock cutting Jan. 4—120
Offset turning relieves form cutters Oct. 25—160
Standard milling cutter forms large radius Feb. 1—126
Threaded arbor saves straddle-mill setup time Apr. 26—138
George, S. Simple repair for broach puller Oct. 11—174
Gerber, H. J. Center positioning gage for angular wheel-truing Mar. 1—127
Double V-gage centers drills to drill round stock Mar. 15—167
"Duplicator" eases die layout Nov. 22—151
Guided punch speeds layout Oct. 11—172
Half-twist helps match butt ends of saw blades Mar. 15—167
Internal "steadyrest" cuts boring bar chatter June 21—147
Simple rotary shear on lathe July 5—152
Slot for indexing plate locating. Nov. 22—148
Two blade cutoff tool Dec. 20—120
Work-driving without a dog Oct. 25—163
Gifford, Henry Attachment to shaper cuts hand work on punches Feb. 15—166
Cartridge units for adjustable drillhead Aug. 16—148
Know your magnetic chucks July 5—122
One-piece hammer and crank tightens milling vises Jan. 4—118
Rotating toolholder shapes die openings Mar. 1—126
Giglio, Leonard Barrel finishing . . . more art than science Mar. 15—125

(ed) Editorial (P.I.) Practical Ideas

Glaeser, George Ti-stainless machined like butter ..... Sept. 13—144
Glick, Phillip & A. J. Langhammer Machining powder-metal parts is easy, if . . . Apr. 26—101
Goldrath, Bert Bicycle sprockets help small crane move freely ..... June 7—158
Inexpensive shop-made sheet metal rolling machine ..... July 19—148
Gould, A. G. Adjustable toolblocks speed setups ..... Sept. 13—183
Conversion capers speed threading and drilling ..... Dec. 20—109
Graves, L. F. & H. W. Lindsay Canny bulk handling saves chip and oil wastes Mar. 15—130
Green, H. T. Gang-cutters speed plug hexing ..... Sept. 27—144
Green, W. J. Radial drill graduates table June 21—146
Gregg, Herbert V. Gear-hob tolerances Pts. 1 & 2 Nov. 22—157, Pts. 3 & 4 Dec. 6—179
Gresens, Howard J. Make your own engineers ..... Feb. 15—127
Gupta, M. L. Setup bores large work on lathe with short bed ..... Dec. 6—176

HAHNE, S. Rotating guide-block aids taper cut ..... Aug. 2—138
Hall, Bert A. Shop thief ..... Mar. 15—156
Halliday, W. M. Self-centralizing clamp aids milling flats ..... Dec. 20—117
Harding, H. V. & others Electrical-discharge machining ..... Mar. 15—137-148
Harrington, Larry Three-position boring bar speeds setups ..... Aug. 30—115
Hartmann, William Adapter releases tubing die ..... Dec. 20—116
Stud extends cutoff table ..... Dec. 20—120
Harwood, J. E. Single-point tool mills spherical bore ..... Mar. 29—129
Heath, John M. Drilled plate aids layout of equidistant holes ..... May 24—151
Old gear makes dividing-head lathe . . Aug. 16—147
Titanium scriber marks lines on glass Mar. 1—125
Heiser, George H. The Big Wind . . . a problem in huge construction July 19—142
Henriksen, Erik K. Balanced design will fit the chip breaker to the job . . . Apr. 26—118
How to select chip breakers Pts. 1, 2 & 3 ..... May 10—179
Herzl, Giroa Fixture helps polish small-diameter pivots ..... May 24—151
Hicks, Tyler Chart for threading time . . Mar. 1—135
Minimum economical lot sizes . Feb. 15—171
Hildreth, Richard S. Gear-cutting savvy in 16 easy steps ..... Mar. 29— 99
Hoff, Carl Threaded arbor unsticks work Oct. 25—160
Hogg, A. V. H-beam supports yokes for easy drilling ..... Mar. 1—127
Holmdahl, H. W. Formula aids cutting double lead threads ..... Jan. 4—117
Formula for multiple-lead threads speeds shop calculating ..... Oct. 25—164
Holmes, R. W. Trepan bottoming holes in one operation ..... Aug. 16—120
Vacuum chuck and special table increase milling machine range ..... Apr. 12—210
Huber, Walter New uses for trunnion fixtures on your radials ..... Apr. 26—112
Hudson, J. A. Oil for power steering tests purified and re-used ..... Aug. 30— 92

ISETTS, R. Avoid rust on small tools with camphor ..... Mar. 29—129
Chalk aids filing ..... Mar. 15—167
Needle bearings make excellent scribers Feb. 15—165

JACKSON, THEODORE How to pass the word ..... ? ..... July 5—148
James, H. M. Hinged toolholder planes parallel grooves ..... Sept. 13—181
Jehring, J. J. Are you a visual or a verbal man? ..... Dec. 6—129
Jensen, Carl Copper sulfate as an aid to machining operations ..... Nov. 22—149
Inexpensive gage helps match tapers . . Feb. 1—124
Special cutting heads finish 1066 holes May 10—173
Tool steel milling inserts machine valve faces ..... Dec. 20—119
Jonas, A. Tapered shims aid grinding die clearances ..... Oct. 11—176
Jones, Arthur H. Product-market diversification ..... Aug. 16—130
Jones, Robert S. We cut production time 27% with wage incentives . . May 24—118
Jones, W. D. Sheet metals can be made from metal powder ..... June 7—142

KARFUNKEL, MAX Threaded stud aids tapered reamer ..... Dec. 6—175
Kaufman, A. R., P. L. Lowenstein & S. V. Arnold Beryllium—next wonder metal? ..... Apr. 12—203
Kennicott, W. L. Reasons for carbide-tool failure Pts. 1, 2 & 3 June 21—159, Pts. 4, 5 & 6 ..... July 5—155
King, Don R. Production should supervise quality control ..... July 19—128
Punch and die clearance ..... Apr. 12—245
Kirk, Laurence H. Eight ways to make pneumatics practical ..... June 21—130
Kline, Kenneth L. Put standard minutes to work ..... Mar. 1—106
Kluge, W. T. How to form integrally stiffened skins ..... Nov. 22—129
Kokoskin, W. J. Watch jig operating costs Pts. 1 & 2 ..... Feb. 15—173
Koonter, Carl Ten steps make sports-car tailpipes ..... Oct. 25—158
Kopacz, S. Precision limit switches for production gaging ..... May 24—152
Koslow, G. H. Another way to lock vises . . Apr. 26—139
Hand tapping angle iron speeded with "brace and bit" ..... Jan. 4—116
Inexpensive boring head ..... July 5—151
Simple tailstock attachment aids aluminum tube cutoff ..... May 10—175
Starter-motor parts aid experimental work ..... Mar. 29—128
Krabacher, E. J. Grinding titanium no longer a problem ..... June 21—124
Krabacher, E. J. & others. Titanium is unorthodox when machined . . . here's why ..... July 5—118
Kunkleman, Herbert P. Two ways to mill curved slots ..... Aug. 2—110

LAL, MANOHAR Pinion-drive turns cone taper ..... Dec. 6—176
Langhammer, A. J. & Phillip Glick Machining powder-metal parts is easy, if . . . . Apr. 26—101
Lawler, W. J. & V. F. Binkley Stretch aluminum plate to reduce machining distortion ..... Mar. 15—128
Lawrence, Fred Eccentric-driven, gearless multiple-drill head ..... Feb. 1—127
Leave, Harry N. A new look at cutting fluids ..... Mar. 1— 97
Lee, Charles G. Just spin them in salt. May 10—132
Lee, G. Inexpensive shop comparator measures to 0.0001 in. ..... Dec. 20—118
LeGrand, Rupert & Anderson Ashburn How to work steel ..... Mid-Nov.—33-160
Lennon, F. J. Jr. Belt finishing of carbide tools proves effective ..... Feb. 1—104
Lettino, Fred Bicycle improves hammer . . . . Feb. 1—124
Tray on vises saves wear on slide . . . Oct. 25—161
Leuthner, F. G. & C. P. Spiez Silver brazing goes semi-automatic ..... May 10—121
Levitt, Albert L. Holes pulverized in plastics Oct. 11—144
Tubing cutoff method ..... Aug. 16—148
Lindbeck, S. L. To machine radioactive materials ..... Apr. 12—166
Lindsay, H. W. & L. F. Graves Canny bulk handling saves chip and oil wastes . . . Mar. 15—130
Lineback, Hugh Candle helps soft-metal grinding ..... Oct. 25—162
Linsley, H. E. A handbook of workholding devices Pt. 2 Stationary devices Oct. 11—145-160
How to babbitt a large bearing. Aug. 30— 98
Lisberger, Daniel S. Air speeds control-device assembly ..... Aug. 16—126
Liska, A. G. Hold-down screw blocks effective on planers ..... Nov. 22—152
Loewer E. G., M. C. Shaw & N. H. Cook Machine-tool dynamometers . . . a current appraisal ..... May 10—125
Long, R. A. Now titanium can be furnace-brazed ..... Aug. 16—117
Lorain, Dan, Jr. & A. M. Troyer Automatic welding fixture ..... Apr. 26—108
Lowenstein, P. L., A. R. Kaufman & S. V. Arnold Beryllium — next wonder metal? ..... Apr. 12—203

MACPHAIL, BURNS S. Dodge gages V-8 bores in the machine shop. Oct. 11—134
Martin, C. L. Slot in thread cleans bolts Mar. 1—128
Martin, Roy Tubular parts are welded automatically ..... Sept. 27—119
Mason, J. P. & E. B. Weber Foam cooling clings ..... Apr. 12—174
Mate, Joseph Bandsaw welder butt-welds small drill extensions ..... May 10—174
Matthewman, J. M. Versatile producer . . . the press brake Pt. 2 Jan. 4—96, Pt. 3 Feb. 1—108, Pt. 4 Nov. 22—116
Matulaitis, V. E. Electrical-discharge machining ..... Mar. 15—137-148
McAllister, H. N. Inexpensive boring bar holder ..... July 19—147
McBee, Frank W. & M. L. Begeman Spot welds work well in titanium Dec. 20— 98
McCafferty, John Easily constructed fly-cutter ..... Aug. 2—140
Indicator center-finder ..... Sept. 13—183
McKean, Martin & Walter White Hard chrome plate pays unexpected dividends ..... Aug. 16—142
Menkin, Burnett Endless coil spring activates stripper fingers ..... Apr. 12—213
Merchant, M. E. & others Titanium is unorthodox when machined . . . here's why ..... July 5—118
Mernieks, F. Sandwich helps drill semi-circular holes ..... Mar. 1—125
Miekley, E. M. Gas burners braze turbine blades ..... Dec. 6—170
Miller, J. H. & others Titanium is unorthodox when machined . . . here's why July 5—118
Milner, G. R. Ring nut fastening method Oct. 11—173
Slots indicate fixture distortion. Dec. 6—173
When using a lockscrew ..... Dec. 20—117
Modd, C. M. A little design change saved a lot of money ..... Feb. 1—103
Molloy, Clifford Double-toolholder aids cutting of oil groves ..... Apr. 12—216
Improvised six-station drillpress speeds single-spindle work ..... Apr. 12—140
Improvised "slotting machine" speeds work on plates ..... May 10—176
Ratchet speeds shaper work July 19—145
Wound-up form tool unwinds to cut contours ..... Feb. 15—164
Moore, D. Floating reamer-holder for knee tools ..... Aug. 30—116
Morgan, C. L. Personal interest and guards . . . cut accidents, boost production. Sept. 13—178
Morgan, I. W. Guided rings checks tapers. Mar. 29—129
Morgan, W. J. Mandrel matches angle iron. Aug. 16—147
Moser, F. To center a keyseat cutter . Apr. 26—138
Murro, Haim Etching weakens springs to specifications ..... Feb. 1—125
Hexagonal recess with screwhead grip. Feb. 15—164
Roller-chain links for odd jobs . Mar. 29—127
Shaper attachment generates bevel gears. Mar. 1—122
Muth, John Air press and threaded die put threads on sheet metal ..... Apr. 12—216
Circular helix formed in one die operation ..... Mar. 29—128

NICHOLS, C. A. Get your special machines off to a good start . . . Feb. 15—121
Nikolais, John R. Press-replacement study pays off for spring maker . . . Dec. 20—130
Nolle, D. G. Ball-bearing locks on fixture aid turning of ordnance shells . . . May 24—152
Norko, George S. Bench lathe fixture speeds capillary tube cutoff ..... Sept. 27—144

O'CONNELL, FRANK Carbide-tipped finger gages cutoff tubing lengths. Sept. 13—184
Odiorne, George S. Get returns from foreman training ..... Dec. 6—137
Olson, Elof B. Eccentric-driven gearless multiple drillhead ..... Mar. 1—127
Olson, S. E. Five-station progressive die forms and cuts off caps ..... June 7—159
Ousley, W. K. Why . . . production-wise, plant-protection foolish? ..... May 24—146
Oxford, Carl J. Jr. 'Flying stop' shows drill cutting action ..... Mar. 1—102

PAQUIN, J. R. Formulas for adjacent triangles ..... Jan. 18—267
Paret, Richard E. How to work stainless steel ..... Sept. 27—129-140
Parsons, M. L. Ball-bearing telescoping drive. Aug. 30—114
Pasternak, Stephen F. Cam feed speeds undercutting on 75-mm shell . . . Apr. 26—110
Patel, A. Y. Frames support inside micrometers ..... Dec. 20—119
Penn, John A. How Navy probes bores. Mar. 15—160
Peterson, R. O. How to choose power brushes Pts 1, 2 & 3 ..... Oct. 25—167
Pethybridge, Charles A. Tooth-by-tooth induction hardening multiplies gear strength and life ..... Oct. 25—117
Piekos, Frank E. Contacts in fixtures assure repetitive accuracy ..... Oct. 11—136
Pierson, Dr. Orville L. How to machine acrylic plastics ..... Feb. 1—113-120

QUINN, E. Gaging method eases making dovetail form tools ..... Dec. 6—172

RAMM, HENRY H. Slotted aluminum step chuck holds small rings Aug. 30—115
Reid, James W. Simplified static balancing Pts 1 & 2 ..... Oct. 11—179
Rheim, J. E. How Rohr heats dies to form titanium ..... Oct. 11—161
Rhodenbaugh, Harold "Plaster cast" solves tough deburring problem . . . May 24—149
Riley, F. E. Automatic polishing machine. June 21—145
Ring, Ward A. Conveyors and telephones speed schedules ..... Sept. 13—134
Robie, Norman P. Take your pick of a million grinding wheels ..... Aug. 2—114
Roderick, G. W. Form tool "drills" dozen 0.013-in. holes ..... July 19—145
Roed, Erik Thin lead plate measures die-opening dimensions ..... May 24—150
Roedder, Robert Spring wire aids checking depths ..... Apr. 12—213
Rogers, G. H. Guided tool in offset holder aids turning OD of large hub. Nov. 22—149
Rollin, James H. In-place babbitting aids spotfacing large casting ..... Mar. 15—164

(ed) Editorial (P.I.) Practical Ideas

Rosato, Nicholas & S. E. Siemen Trepanning titanium saves time and material. Aug. 30— 89

Rose, Joseph W. How to work tomorrow's metals — tantalum and columbium Apr. 12—189

Rosenbaum, H. H. How Convair tools with plastics Mar. 15—121

Roses, A. F. Offset compound eases work in close tolerances Feb. 1—127

Ross, Herbert F. Self ejecting chuck wrench. Sept. 27—142

Rotroff, Virgil H. What makes suggestion plans work? July 19—144

SAARI, OLIVER Contact ratios for undercut gear teeth Pts 1 & 2 Jan. 18—269

Dashpot dampens dynamometer vibrations Jan. 4—116

Difference curves solve form-tool corrections Pts. 1, 2 & 3 Mar. 15—171

Form cutters for helical gears Pts. 1 & 2 Feb. 1—131

How to calculate exact wheel profiles for form grinding helical gear teeth. Sept. 13—172

How to calculate "metal-to-metal" involute gears Dec. 20— 89

Nomograph aids solution of worm-thread profiles July 5—113

Sachs, Frank New Russian concept of cutting tools . . . true or false? Apr. 12—170

Saiia, Louis Rotating flycutter mills spheres with singlepoint tool Apr. 26—136

Sams, Denver & Joseph Borodavchuk Spin re-entrant shapes Feb. 15—145

Satterlee. Roland Conventional tools machine titanium Aug. 30— 94

Schaper, Leonard & Charles Gentile How to centerless-grind parts of plastic and wood rod May 10—134

Schlindwein, J. G. Cut costs with die-shim perforators Sept. 27—123

Diesel "take-apart" cart saves time, cuts die damage Mar. 1—110

Hardened guides eject slug problems. Mar. 15—163

Hush up your ejector racket Sept. 13—180

Schmidt, Edward Eccentric-lock drillpress fixture speeds second operation. Apr. 12—214

Milling fixture for flats on drills. Aug. 30—114

Schofield, Jack "Wicking gun" helps insert wicks into bearings Sept. 13—181

Schroeder, Carl A. Practical "lab" tests light . . . and quiet May 24—124

Schug, William W. Good tooling plus dial feeds will cut stamping costs Oct 11—129

Schwartz, Charles Three leaf springs support thin-walled redraw work Apr. 26—140

Schwartz, John N. Drillrod helps dowel removal June 7—158

Scale speeds bandsaw work Apr. 12—216

Schwartz, N. Split spring-steel retaining ring gives close die stripping Dec. 6—172

Scott, David Russians apply automation to 20-yr.-old machines Oct. 11—164

Standardization characterizes communist-built machine tools Feb. 15—158

Sdano, Jesse G. Mist cooling systems improve machining operations Aug. 2—117

Selby, Corwin S. Some tricks in making electron plumbing Feb. 15—134

UHF contacts formed four times faster. Feb. 1— 97

Shallenberger, Frank K. Is shell molding practical for job lots? Oct. 25—130

Shaw, M. C., N. H. Cook & E. G. Loewen Machine-tool dynamometers . . . a current appraisal May 10—125

Sheets, Robert New wrinkles for an old plant June 7—129

Siebold, Ernest F. Bench tool knurls piano wire Aug. 2-139

Siemen, S. E. & Nicholas Rosato Trepanning titanium saves time and material Aug. 30— 89

Singh, Gurbachan Shaper doubles as surface grinder Dec. 6—173

Smalenberger, Edward Hardwood boards straighten small tubes May 24—149

Spiesz, C. P. & F. G. Leuthner Silver brazing goes semi-automatic May 10—121

Sporck, Claus L. Roll flowing saves operations and conserves materials Mar. 29—104

Stedman, W. J. Formula for ellipse layout. July 5—152

Steibel, James P. Soft touch for small-hole drilling Sept. 13—138

Stewart, J. Threaded plug starts cut at correct radial position Feb. 15—168

Stocker, William M. Jr. High-speed trepanning Jan. 4—105-114

How to nickel-plate aluminum for solder joining June 7—154

Pick-a-back tooling machines forgings for giant press July 19—117

Process evaluation pays long-term dividends June 21—133

Production tools for precision June 21—117

Screw-machine converted for gun-drilling. Feb. 15—162

Supervisors for tomorrow Aug. 16—133-140

Stocker, W. M. Jr. & C. D. Emerson Numerical control, what it means to metalworking Oct. 25—133-156

Stoke, R. C. & others Electrical-discharge machining Mar. 15—137-148

Storchheim, Samuel How to understand annealing and hot working of metals. Sept. 13—161-168

How to understand cold working of metals Aug. 30—101-108

How to understand heat-treatment processes Apr. 26—125

Stougaard, Chris 45° mounting brakes locating ball versatile June 7—158

Output shaft of differential controls speed from 0 to 300 RMP Mar. 1—127

Simple scale measures compression and tension Apr. 26—137

Strasser, Federico Copper "shim" opens tapped holes May 10—173

Diemakers' kinks Mar. 15—157; Apr. 12—202; May 10—129; June 21—123; July 5—147; July 19—129; Aug. 16—129; Sept. 13—175; Dec. 6—141

Drill jig cuts non-productive time when loading work Dec. 20—117

Erasers support thin parallels June 21—145

Formula aids spring-winding June 7—160

Magazine feed speeds second operations. Mar. 15—165

Repair for threading dies Dec. 20—120

"Safety sheet" avoids overload on blanking and forming press Dec. 20—120

Side cams on assembly die speed switch assembly Aug. 16—145

Simple locknut method Apr. 26—136

Simple wire-bending die June 21—147

Stresau, Ann It's not the weather . . . Dec. 20—114

Stuart, C. W. & C. R. Terry Lathe-chuck crane aids handling, storage Nov. 22—148

Stuart, V. Lucite stripper for locating. Aug. 30—113

Sumption, F. H. Serrated depth-stop speeds stainless drilling Oct. 11—176

Sweet, Donald E. Normal thread angles and bottom flats (Acme) Pts. 1 & 2. Sept. 27—147

Plug constants for checking dovetails. Aug. 30—123

Slotting-cutter runout Sept. 27—151

TANGERMAN, E. J. Automation . . . combines standard lathes Mar. 29—110

Carbide bur "grinds" radius slot on hardened 8713 steel Apr. 12—172

How tools made the world in which we live Dec. 20—101

Railroad axles roller-bearinged at freight-car production speeds Jan. 4—130

Work cuts tool, tool forms work . . . with ultrasonics Aug. 30— 85

Taylor, E. Honeycomb fixture holds rings flat during quenching Aug. 16—146

Terry, C. R. & C. W. Stuart Lathe-chuck crane aids handling, storage Nov. 22—148

Thibault, Dr. N. W. & B. H. Anderson Why line your sludge tank with diamonds? Feb. 15—154

Thuerwachter, W. C. Mist cooling helps some planer jobs Aug. 2—129

Thuma, Richard F. Mist cooling systems improve machining operations Aug. 2—117

Thweatt, H. D. How to choose hydraulic presses for metal forming operations. Mar. 29—115-126

Tiefel, L. W. You can miter strip stock, too. Oct. 11—139

Titus, R. M. Mist cooling helps some planer jobs Aug. 2—129

Trigger, Kenneth J. Thermal number measures efficiency of metal cutting. June 7—145-152

Trimailo, Walter Right-angle V-block for circular layout Feb. 15—167

Tullis, Lyell C. Exposing machine-tool gremlins with high-speed photography. June 7—156

Troyer, A. M. & Dan Loraine, Jr. Automatic welding fixture Apr. 26—108

VALE, R. G. Compensated angles add life to complicated form tools Apr. 12—215

Vetsch, A. Gage bar checks tension for press setup Feb. 1—127

Ingenious holding method helps mill helical groove June 7—157

Volkert, John Apprentices training program. Apr. 26—156

WALLACE, J. W. Flexible tool support aids cutting tapered hole July 5—150

Wain, Jaan Simple device gages vise-held work Oct. 25—164

Walz, Arnold Hard bronze draws stainless without scratches Aug. 2—106

Warner, Robert W. Ball-bearing steadyrest cuts marking, friction Mar. 15—168

Weidenhoft, Robert "Vacuum" chuck holds thin strip for grinding Sept 27—142

Weidner, C. B. Simple contour-milling attachment July 5—149

Wencek, Stanley Kick-press speeds rivet-cutting June 7—157

Wernberg, Gus Cutting fluid to cure bad tap breakage or poor reaming finishes. Mar. 15—167

Disconnected worm speeds alignment. Feb. 1—126

Layout dye measures surface for milling. July 19—146

Whipple, Norman L. Hand forming—machine style Nov. 22—141

Whitcomb, C. E. Another square-end cutoff die Feb. 1—128

White, E. Dalton Rebuilt 50-ton press burnishes axle housings Mar. 1—125

White, Walter, & Martin McKean Hard chrome plate pays unexpected dividends Aug. 16—142

Wiedenholt, Robert Notched parallels for magnetic tables Aug. 16—145

Planetary fixture mills flats in position in turret lathe Mar. 15—166

Wiken, C. A. Drill units move tools to work, not work to tools May 24—122

Wildhaber, Ernest A new look at wormgear hobbing June 21—149

Wilson, George W. Eccentric-mounted mandrel relieves form cutters Aug. 2—139

Winch, Clarence B. Drillpress turns small stock Sept. 27—143

Winchell, Sterling "Excess rejects" spot process troubles Oct. 11—142

Wing, W. Paul Diamond pin design. Mar. 29—137

Winter, W. C. Special tools support 14,000-ton extrusion press Dec. 6—162

Wischhusen, John Gas-welding hard surfaces for precisions May 24—126

Wittlinger, Oscar Hoist and rack handle milling heads Oct. 11—173

Wright, John P. Artists sculpture mica dies. Sept. 13—145-160

How optics replace costly, time-consuming inspection Apr. 12—168

Intricate investment castings require shop "savvy" Nov. 22—120

Non-cylindrical contours . . . how you can grind them May 10—137

YAMAGUCHI, M. Half-piercing locates parts for rivets or welding Mar. 15—166

Side-drilling in turret lathe drills work in place Feb. 1—125

Slide attached to shear catches workpieces Mar. 15—166

Yeager, Water Sr. "Dividing-head" device checks complex electronic parts. May 10—176

Young, H. W. & others Titanium is unorthodox when machined . . . here's why. July 5—118

ZILCH, J. Knurled screwdriver blade. Oct. 25—162

Zmunda, Mike Stopping-disk insert saves setup time Sept. 13—184

Zorich, I. Circular form-tool corrections. Mar. 29—135

Corrections for flat form tools Mar. 29—133

Zurlo, John T. Air motor in tailstock adds to small-drill speed Sept. 27—143

Toolpost-mounted air sander burnishes hydraulic ram June 21—146

(ed) Editorial (P.I.) Practical Ideas